

Model-Specific Compatibility Notes [08/07/2014]:

TSSU-36-08: Will not work with a flat lid “night cover,” there is not enough room between the flat lid and the edge of the countertop to place the service shelf bracket.

TUC-36: N/A

TWT-36: N/A

TUC-36F: N/A

TWT-36F: N/A

TSSU-36-08-LP: Will not work with a flat lid “night cover,” there is not enough room between the flat lid and the edge of the countertop to place the service shelf bracket.

TUC-36-LP: N/A

TWT-36LP: N/A