Model-Specific Compatibility Notes [02/21/2017]:

TWT-60D-4: N/A

TUC-60G: N/A

TSSU-60-12: Will not work with a flat lid "night cover" there is not enough room between the flat lid and

the edge of the countertop to place the service shelf bracket.

TSSU-60-10: Will not work with a flat lid "night cover" there is not enough room between the flat lid and

the edge of the countertop to place the service shelf bracket.

TUC-60D-2: N/A

TSSU-60-24MB-DS: Will not work with a flat lid "night cover" there is not enough room between the flat

lid and the edge of the countertop to place the service shelf bracket.

TUC-60F: N/A

TUC-60D-4: N/A

TUC-60: N/A

TWT-60: N/A

TSSU-60-14: Will not work with a flat lid "night cover" there is not enough room between the flat lid and

the edge of the countertop to place the service shelf bracket.

TWT-60F: N/A

TSSU-60-08: Will not work with a flat lid "night cover" there is not enough room between the flat lid and

the edge of the countertop to place the service shelf bracket.

TWT-60G: N/A

TSSU-60-08-LP: Will not work with a flat lid "night cover" there is not enough room between the flat lid

and the edge of the countertop to place the service shelf bracket.

TSSU-60-12-LP: Will not work with a flat lid "night cover" there is not enough room between the flat lid

and the edge of the countertop to place the service shelf bracket.

TSSU-60-24MB-DS-LP: Will not work with a flat lid "night cover" there is not enough room between the

flat lid and the edge of the countertop to place the service shelf bracket.

TUC-60-LP: N/A

TUC-60G-LP: N/A

TUC-60D-4-LP: N/A

TWT-60LP: N/A

TWT-60D-4-LP: N/A

TUC-60F-LP: N/A

TWT-60D-2: N/A

TWT-60D-2-LP: N/A

TUC-60D-2-LP: N/A

TSSU-60-24M-B-DS-ST: Will not work with a flat lid "night cover" there is not enough room between the flat lid and the edge of the countertop to place the service shelf bracket.

TSSU-60-08D-2: Will not work with a flat lid "night cover" there is not enough room between the flat lid and the edge of the countertop to place the service shelf bracket.

TUC-60G~FDG01: Will not work with a flat lid "night cover" there is not enough room between the flat lid and the edge of the countertop to place the service shelf bracket.