

Model-Specific Compatibility Notes [07/09/2014]:

TWT-72F: N/A

TUC-72: N/A

TUC-72F: N/A

TSSU-72-30MB-DS: Will not work with a flat lid “night cover” there is not enough room between the flat lid and the edge of the countertop to place the service shelf bracket.

TWT-72: N/A

TSSU-72-18: Will not work with a flat lid “night cover” there is not enough room between the flat lid and the edge of the countertop to place the service shelf bracket.

TSSU-72-10: Will not work with a flat lid “night cover” there is not enough room between the flat lid and the edge of the countertop to place the service shelf bracket.

TSSU-72-18-ST: Will not work with a flat lid “night cover” there is not enough room between the flat lid and the edge of the countertop to place the service shelf bracket.

TSSU-72-30M-B-DS-ST: Will not work with a flat lid “night cover” there is not enough room between the flat lid and the edge of the countertop to place the service shelf bracket.

TSSU-72-16: Will not work with a flat lid “night cover” there is not enough room between the flat lid and the edge of the countertop to place the service shelf bracket.

TSSU-72-12: Will not work with a flat lid “night cover” there is not enough room between the flat lid and the edge of the countertop to place the service shelf bracket.

TSSU-72-08: Will not work with a flat lid “night cover” there is not enough room between the flat lid and the edge of the countertop to place the service shelf bracket.