

Model-Specific Compatibility Notes [11/10/2014]:

T-72-6: 115v used after 12/7/2008 (pcn #4148).

TR2R-4HS: Used after 6/12/11 production date or ser no. 1-71710625 per pcn 5032.

T-72G-6: 115v used after 12/7/2008 (pcn #4148).

TS-72-6: 115v used after 12/7/2008 (pcn #4148).

TMC-49: Used after 1/3/10 production date per pcn 4488. Requires 1 fan motor.

TMC-58-DS: Used after 1/3/10 production date or serial #5329275 per pcn 4488. Requires 1 fan motor.

TR2F-2S: (pcn #4050/4720) replaces/retrofits the 800455 motor which was used 1/14/2009. 2 per cabinet.

TR3F-6HS: (pcn #4720) replaces/retrofits the 800455 motor which was used after 10/2/2006. 4 per cabinet.

GDM-33CPT-54: Used between 12/27/2006 and 9/7/2010 (pcn #4610).

GDM-41SL-54: Used between 3/2/2010 w/ Embraco compressor (pcn #4461) and 7/6/14 per pcn 7793. Check work order for correct compressor. **need to check for correct motor** some units were produced between 1/22/13 and 1/31/13 with #948822 and these need to be replaced with the 948822 (will not retrofit).

TS-72: 115v used after 12/7/2008 (pcn #4148).

TR3F-3S: (pcn #4720) replaces/retrofits the 800455 motor which was used after 10/2/2006. 4 per cabinet.

TMC-58: Used after 1/3/10 production date per pcn 4488. Requires 1 fan motor.

T-72G: 115v used after 12/7/2008 (pcn #4148).

TS-72-3-G-3: 115v used after 12/7/2008 (pcn #4148).

TR2FRI-2S: 115v only used before 11/1/11 production or before 1-7284923 per pcn 5413. (pcn #4720) replaces/retrofits the 800455 motor which was previously used. 2 per cabinet.

T-72: 115v used after 12/7/2008 (pcn #4148).

TMC-49-DS: Used after 1/3/10 production date per pcn 4488. Requires 1 fan motor.

GDM-35SL-RF: Used after 3/1/2010 (pcn #4471).

GDM-14RF: Used after 12/27/2009 (pcn #4451).

TR2FPT-2S-2S: (pcn #4720) replaces/retrofits the 800455 motor which was previously used. 2 per cabinet.

TS-72G-6: 115v used after 12/7/2008 (pcn #4148).

T-72-3-G-3: 115v used after 12/7/2008 (pcn #4148).

TMC-34: Used after 1/3/2010 w/ Embraco compressor (pcn #4488) requires 1 fan motor.

GDM-41SL-60: Used between 3/13/2011 (pcn #4852) - 7/18/11 (pcn 5158).

TR2F-4HS: (pcn #4050/4720) replaces/retrofits the 800455 motor which was used after 1/14/2009. 2 per cabinet.

TR2R-2S: Used after 6/12/11 production date or ser no. 1-71710625 per pcn 5032.

TS-72G: 115v used after 12/7/2008 (pcn #4148).

TA1FRI-1S: (pcn #4720) replaces/retrofits the 800455 motor which was previously used. 2 per cabinet.

TA2F-2S: (pcn #4050/4720) replaces/retrofits the 800455 motor which was used after 1/14/2009. 2 per cabinet.

TA2F-4HS: (pcn #4050/4720) replaces/retrofits the 800455 motor which was used after 1/14/2009. 2 per cabinet.

TA2FPT-2S-2S: (pcn #4720) replaces/retrofits the 800455 motor which was previously used. 2 per cabinet.

TA2R-2S: Used after 6/12/11 production date or ser no. 1-71710625 per pcn 5032.

TA2R-4HS: Used after 6/12/11 production date or ser no. 1-71710625 per pcn 5032.

TA3F-3S: (pcn #4720) replaces/retrofits the 800455 motor which was used after 10/2/2006. 4 per cabinet.

TA3F-6HS: (pcn #4720) replaces/retrofits the 800455 motor which was used after 10/2/2006. 4 per cabinet.

TG1FRI-1S: (pcn #4720) replaces/retrofits the 800455 motor which was previously used. 2 per cabinet.

TG2F-2S: (pcn #4050/4720) replaces/retrofits the 800455 motor which was used after 1/14/2009. 2 per cabinet.

TG2F-4HS: (pcn #4050/4720) replaces/retrofits the 800455 motor which was used after 1/14/2009. 2 per cabinet.

TG2FPT-2S-2S: (pcn #4720) replaces/retrofits the 800455 motor which was previously used. 2 per cabinet.

TG2R-2S: Used after 6/12/11 production date or ser no. 1-71710625 per pcn 5032.

TG2R-4HS: Used after 6/12/11 production date or ser no. 1-71710625 per pcn 5032.

TG3F-3S: (pcn #4720) replaces/retrofits the 800455 motor which was used after 10/2/2006. 4 per cabinet.

TG3F-6HS: (pcn #4720) replaces/retrofits the 800455 motor which was used after 10/2/2006. 4 per cabinet.

TR1FRI-1S: (pcn #4720) replaces/retrofits the 800455 motor which was previously used. 2 per cabinet.

GDM-52TM-RL: Used after 3/27/2011 (pcn #4900) two per cabinet.

TR-37RI-F: (pcn #4720) replaces/retrofits the 800455 motor which was previously used. 2 per cabinet.

TR1F-1G: (pcn #4720) replaces/retrofits the 800455 motor which was used after 4/10/2005. 2 per cabinet.

TA1F-1G: (pcn #4720) replaces/retrofits the 800455 motor which was used after 4/10/2005. 2 per cabinet.

TG1F-1G: (pcn #4720) replaces/retrofits the 800455 motor which was used after 4/10/2005. 2 per cabinet.

TR2F-2G: (pcn #4720) replaces/retrofits the 800455 motor which was used 1/19/2005. 2 per cabinet.

TA2F-2G: (pcn #4720) replaces/retrofits the 800455 motor which was used after 1/19/2005. 2 per cabinet.

TG2F-2G: (pcn #4720) replaces/retrofits the 800455 motor which was used after 1/19/2005. 2 per cabinet.

TR1-F-2HG: (pcn #4720) replaces/retrofits the 800455 motor which was used after 4/10/2005. 2 per cabinet.

TA1-FPT-2HS-2HS: (pcn #4720) replaces/retrofits the 800455 motor which was previously used. 2 per cabinet.

TA1-F-1S STARBUCKS: (pcn #4720) replaces/retrofits the 800455 motor which was previously used. 2 per cabinet.

TA2-F-2S STARBUCKS: (pcn #4050/4720) replaces/retrofits the 800455 motor which was used after 1/14/2009. 2 per cabinet.

TA2-R-2S STARBUCKS: Used after 6/12/11 production date or ser no. 1-71710625 per pcn 5032.

TR1FPT-1S-1S: (pcn #4720) replaces/retrofits the 800455 motor which was previously used. 2 per cabinet.

TA1-FPT-1S-1S: (pcn #4720) replaces/retrofits the 800455 motor which was previously used. 2 per cabinet.

TG1FPT-1S-1S: (pcn #4720) replaces/retrofits the 800455 motor which was previously used. 2 per cabinet.

TMC-34-DS: Used after 1/3/2010 w/ Embraco compressor (pcn #4488) requires 1 fan motor.

TG2R-2S STARBUCKS: Used after 6/12/11 production date or ser no. 1-71710625 per pcn 5032.

TG2F-2S STARBUCKS: (pcn #4720) replaces/retrofits the 800455 motor which was previously used. 2 per cabinet.

TG1F-1S STARBUCKS: (pcn #4720) replaces/retrofits the 800455 motor which was previously used. 2 per cabinet.

TG1F-1HG/1HS: (pcn #4720) replaces/retrofits the 800455 motor which was used after 4/10/2005. 2 per cabinet.

TMC-34-S-DS: Used after 1/3/2010 w/ Embraco compressor (pcn #4488) requires 1 fan motor.

TMC-34-DS-SS: Used after 1/3/2010 w/ Embraco compressor (pcn #4488) requires 1 fan motor.

TMC-34-S-DS-SS: Used after 1/3/2010 w/ Embraco compressor (pcn #4488) requires 1 fan motor.

TA2FRI-2S: 115v only used before 11/1/11 production or before 1-7284923 per pcn 5413. (pcn #4720) replaces/retrofits the 800455 motor which was previously used. 2 per cabinet.

TR2FPT-4HS-4HS: (pcn #4720) replaces/retrofits the 800455 motor which was previously used. 2 per cabinet.

TG2FRI-2S: 115v only used before 11/1/11 production or before 1-7284923 per pcn 5413. (pcn #4720) replaces/retrofits the 800455 motor which was previously used. 2 per cabinet.

GDM-11SD: N/A

GDM-41SL-54N: Used between 3/2/2010 w/ Embraco compressor (pcn #4461) and 7/6/14 per pcn 7793. Check work order for correct compressor.

TR2F-4HG: (pcn #4720) replaces/retrofits the 800455 motor which was previously used. 2 per cabinet.

TG1F-2HG: (pcn #4720) replaces/retrofits the 800455 motor which was used after 4/10/2005. 2 per cabinet.

STA1FRI-1S: (pcn #4720) replaces/retrofits the 800455 motor which was previously used. 2 per cabinet.