

**Model-Specific Compatibility Notes [09/11/2015]:**

**TDBD-72-2:** Used between 10/11/2006 and 11/1/2010 (pcn #4450). May require relay. Replaces #800320.

**TDBD-72-4:** Used between 10/11/2006 and 11/1/2010 (pcn #4450). May require relay. Replaces #800320.

**TSID-72-2-L:** Used after 10/11/06 production date. May require relay. Replaces #800320.

**TSID-72-4:** Used after 10/11/06 production date. May require relay. Replaces #800320.

**TSID-72-2:** Used after 10/11/06 production date. May require relay. Replaces #800320.

**TSID-72-4-L:** Used after 10/11/06 production date. May require relay. Replaces #800320.

**TSID-72-3-L:** Used after 10/11/06 production date. May require relay. Replaces #800320.

**TSID-72-6-L:** Used after 10/11/06 production date. May require relay. Replaces #800320.

**TSID-72-3:** Used after 10/11/06 production date. May require relay. Replaces #800320.

**TSID-72-6:** Used after 10/11/06 production date. May require relay. Replaces #800320.

**TDBD-48-2:** Used between 10/11/2006 and ~july 2009 (pcn #4322) may require relay. Replaces #800320.

**TDBD-48-4:** Used between 10/11/2006 and ~july 2009 (pcn #4322) may require relay. Replaces #800320.