

978607 Compatibility Notes - 5/17/2018	
Model	Notes
CVM-19T	REPLACES 801723 PCN 7698.
CVM-26	REPLACES 801723 PCN 7698. USED BEFORE 2/5/13 OR SERIAL NUMBER 7677232 PER PCN 6771.
G4SM-23PT	REPLACES 801723 PCN 7698. USE BETWEEN 5/2/05 PRODUCTION DATE AND 7/15/13 OR SERIAL NUMBER 7819220 PER PCN 6998.
GDM-10	REPLACES 801723 PCN 7698. 115V ONLY USED BEFORE 5/13/12 PER PCN 5862.
GDM-10-58	REPLACES 801723 PCN 7698. USED BEFORE 6/8/12 OR SER. NO. 7452827 PER PCN 5933.
GDM-10F	REPLACES 801723 PCN 7698. USED BETWEEN 6/19/11 OR SER. NO. 1-7173025 (MUST BE USED WITH ONE PIECE RADIUS MOLDED GRILL) PCN 4492 - 4997. PER PCN 6342. (NOTE ALL LD LIGHTING AND LAE MODELS WILL USE THIS CORD) AND 11/11/13 PER PCN 7321. STILL USED IN STAINLESS UNIT UNTIL 1/6/14 PER PCN 7357.
GDM-10RF	REPLACES 801723 PCN 7698. 115V ONLY USED BEFORE 5/13/12 PER PCN 5862 .
GDM-10RF-LE	REPLACES 801723 PCN 7698. SEND 881618 KIT FOR BEFORE 10/9/02 PRODUCTION DATE. SEND CORD ONLY AFTER 10/9/02. DIAMETER OF CORD BECAME LARGER. CUSTOMER WILL HAVE TO DRILL HOLE 1/8" LARGER IN BOTTOM OF DOOR TO 39/64", REPLACE STRAIN RELIEF BUSHING, CABLE CLAMP AND GRILL BUSHING.
GDM-10SSL	REPLACES 801723 PCN 7698. SPECIAL APPLICATION ONLY. LED LIGHTING.
GDM-12	REPLACES 801723 PCN 7698. 115V USE BEFORE 5/14/12 PRODUCTION IN BLDG 3 DATE OF SER. NO. 1-7434984 OR BEFOR 5/23/12 PRODUCTION IN MEX. PER PCN 5874. STILL USED ON 208V/220V/CE SPECIAL APPLICATION ONLY. LED LIGHTING.
GDM-12F	REPLACES 801723 PCN 7698. USED BETWEEN 6/19/11 OR SER. NO. 1-7173025 PRODUCTION DATE. MUST BE USED WITH ONE PIECE RADIUS MOLDED GRILL PCN 4492 - 4997. PER PCN 6342. NOTE ALL LD LIGHTING AND LAE MODELS WILL USETHIS CORD AND 11/11/13 PER PCN 7321. STILL USED IN STAINLESS UNIT UNTIL 1/6/14 PER PCN 7357.
GDM-12LE-RF	REPLACES 801723 PCN 7698. SEND 881618 KIT FOR BEFORE 10/9/02 PRODUCTION DATE. SEND CORD ONLY AFTER 10/9/02. DIAMETER OF CORD BECAME LARGER. CUSTOMER WILL HAVE TO DRILL HOLE 1/8" LARGER IN BOTTOM OF DOOR TO 39/64", REPLACE STRAIN RELIEF BUSHING, CABLE CLAMP AND GRILL BUSHING.
GDM-12RF	REPLACES 801723 PCN 7698. SEND 881618KIT FOR BEFORE 10/9/02 PRODUCTION DATE. SEND CORD ONLY AFTER 10/9/02. DIAMETER OF CORD BECAME LARGER. CUSTOMER WILL HAVE TO DRILL HOLE 1/8" LARGER IN BOTTOM OF DOOR TO 39/64", REPLACE STRAIN RELIEF BUSHING, CABLE CLAMP AND GRILL BUSHING.

GDM-14SL	REPLACES 801723 PCN 7698. SEND 881618 KIT FOR BEFORE 10/9/02 PRODUCTION DATE. SEND CORD ONLY AFTER 10/9/02. DIAMETER OF CORD BECAME LARGER. CUSTOMER WILL HAVE TO DRILL HOLE 1/8" LARGER IN BOTTOM OF DOOR TO 39/64", REPLACE STRAIN RELIEF BUSHING, CABLE CLAMP AND GRILL BUSHING.
GDM-19	REPLACES 801723 PCN 7698. SEND 881618 KIT FOR BEFORE 10/9/02 PRODUCTION DATE. SEND CORD ONLY AFTER 10/9/02. DIAMETER OF CORD BECAME LARGER. CUSTOMER WILL HAVE TO DRILL HOLE 1/8" LARGER IN BOTTOM OF DOOR TO 39/64", REPLACE STRAIN RELIEF BUSHING, CABLE CLAMP AND GRILL BUSHING.
GDM-19 220V CE COKE SPAIN	REPLACES 801723 PCN 7698. SEND 881618 KIT FOR BEFORE 10/9/02 PRODUCTION DATE. SEND CORD ONLY AFTER 10/9/02. DIAMETER OF CORD BECAME LARGER. CUSTOMER WILL HAVE TO DRILL HOLE 1/8" LARGER IN BOTTOM OF DOOR TO 39/64", REPLACE STRAIN RELIEF BUSHING, CABLE CLAMP AND GRILL BUSHING.
GDM-19T	REPLACES 801723 PCN 7698. 115V USED BEFORE 1/31/13 PRODUCTION DATE IN B3 & BEFORE 2/4/13 IN MEXICO PER PCN 6675 .
GDM-23	REPLACES 801723 PCN 7698. SEND 881618 KIT FOR BEFORE 10/9/02 PRODUCTION DATE. SEND CORD ONLY AFTER 10/9/02. DIAMETER OF CORD BECAME LARGER. CUSTOMER WILL HAVE TO DRILL HOLE 1/8" LARGER IN BOTTOM OF DOOR TO 39/64", REPLACE STRAIN RELIEF BUSHING, CABLE CLAMP AND GRILL BUSHING.
GDM-23-2	REPLACES 801723 PCN 7698. SEND 881618 KIT FOR BEFORE 10/9/02 PRODUCTION DATE. SEND CORD ONLY AFTER 10/9/02. DIAMETER OF CORD BECAME LARGER. CUSTOMER WILL HAVE TO DRILL HOLE 1/8" LARGER IN BOTTOM OF DOOR TO 39/64", REPLACE STRAIN RELIEF BUSHING, CABLE CLAMP AND GRILL BUSHING. USE 912009 FOR TOP RIGHT DOOR.
GDM-23FC	REPLACES 801723 PCN 7698. .
GDM-23FC-RF	REPLACES 801723 PCN 7698. SEND 881618 KIT FOR BEFORE 10/9/02 PRODUCTION DATE. SEND CORD ONLY AFTER 10/9/02. DIAMETER OF CORD BECAME LARGER. CUSTOMER WILL HAVE TO DRILL HOLE 1/8" LARGER IN BOTTOM OF DOOR TO 39/64", REPLACE STRAIN RELIEF BUSHING, CABLE CLAMP AND GRILL BUSHING.
GDM-23RF	REPLACES 801723 PCN 7698. SEND 881618 KIT FOR BEFORE 10/9/02 PRODUCTION DATE. SEND CORD ONLY AFTER 10/9/02. DIAMETER OF CORD BECAME LARGER. CUSTOMER WILL HAVE TO DRILL HOLE 1/8" LARGER IN BOTTOM OF DOOR TO 39/64", REPLACE STRAIN RELIEF BUSHING, CABLE CLAMP AND GRILL BUSHING.

GDM-23RL	REPLACES 801723 PCN 7698. SEND 881618 KIT FOR BEFORE 10/9/02 PRODUCTION DATE. SEND CORD ONLY AFTER 10/9/02. DIAMETER OF CORD BECAME LARGER. CUSTOMER WILL HAVE TO DRILL HOLE 1/8" LARGER IN BOTTOM OF DOOR TO 39/64", REPLACE STRAIN RELIEF BUSHING, CABLE CLAMP AND GRILL BUSHING.
GDM-23W	REPLACES 801723 PCN 7698. SEND 881618 KIT FOR BEFORE 10/9/02 PRODUCTION DATE. SEND CORD ONLY AFTER 10/9/02. DIAMETER OF CORD BECAME LARGER. CUSTOMER WILL HAVE TO DRILL HOLE 1/8" LARGER IN BOTTOM OF DOOR TO 39/64", REPLACE STRAIN RELIEF BUSHING, CABLE CLAMP AND GRILL BUSHING.
GDM-23W-RF	REPLACES 801723 PCN 7698. SEND 881618 KIT FOR BEFORE 10/9/02 PRODUCTION DATE. SEND CORD ONLY AFTER 10/9/02. DIAMETER OF CORD BECAME LARGER. CUSTOMER WILL HAVE TO DRILL HOLE 1/8" LARGER IN BOTTOM OF DOOR TO 39/64", REPLACE STRAIN RELIEF BUSHING, CABLE CLAMP AND GRILL BUSHING.
GDM-26	REPLACES 801723 PCN 7698. SEND 881618 KIT FOR BEFORE 10/9/02 PRODUCTION DATE. SEND CORD ONLY AFTER 10/9/02. DIAMETER OF CORD BECAME LARGER. CUSTOMER WILL HAVE TO DRILL HOLE 1/8" LARGER IN BOTTOM OF DOOR TO 39/64", REPLACE STRAIN RELIEF BUSHING, CABLE CLAMP AND GRILL BUSHING.
GDM-26RF	REPLACES 801723 PCN 7698. SEND 881618 KIT FOR BEFORE 10/9/02 PRODUCTION DATE. SEND CORD ONLY AFTER 10/9/02. DIAMETER OF CORD BECAME LARGER. CUSTOMER WILL HAVE TO DRILL HOLE 1/8" LARGER IN BOTTOM OF DOOR TO 39/64", REPLACE STRAIN RELIEF BUSHING, CABLE CLAMP AND GRILL BUSHING.
GDM-26W-RF	REPLACES 801723 PCN 7698. SEND 881618 KIT FOR BEFORE 10/9/02 PRODUCTION DATE. SEND CORD ONLY AFTER 10/9/02. DIAMETER OF CORD BECAME LARGER. CUSTOMER WILL HAVE TO DRILL HOLE 1/8" LARGER IN BOTTOM OF DOOR TO 39/64", REPLACE STRAIN RELIEF BUSHING, CABLE CLAMP AND GRILL BUSHING.
GDM-35	REPLACES 801723 PCN 7698. USED BETWEEN 10/9/2002 & 7/13/2006 (PCN #3303) BEFORE 19/9/2002 REPLACE W/ 912009 CORD KIT DUE TO DIAMETER OF THE CORD CHANGING. .
GDM-43	REPLACES 801723 PCN 7698. . USED BEFORE 3/4/14 PER PCN 7578. WENT TO A LONGER CORD AFTER THIS DATE. SEND 881618 KIT FOR BEFORE 10/9/02 PRODUCTION DATE. SEND CORD ONLY AFTER 10/9/02. DIAMETER OF CORD BECAME LARGER. CUSTOMER WILL HAVE TO DRILL HOLE 1/8" LARGER IN BOTTOM OF DOOR TO 39/64", REPLACE STRAIN RELIEF BUSHING, CABLE CLAMP AND GRILL BUSHING.

GDM-49	REPLACES 801723 PCN 7698. USED BEFORE 11/3/05 PRODUCTION DATE (EXCEPT BEFORE 10/9/02 SEND 881618 KIT BECAUSE DIAMETER OF CORD BECAME LARGER CUSTOMER WILL HAVE TO DRILL HOLE 1/8" LARGER IN BOTTOM OF DOOR TO 39/64", REPLACE STRAIN RELIEF BUSHING, CABLE CLAMP AND GRILL BUSHING. CONNECT TO 801732 "Y" CORD.
GDM-49 DOLLAR GENERAL	REPLACES 801723 PCN 7698. USED BETWEEN 10/9/02 & 8/20/04.
GDM-49DT	REPLACES 801723 PCN 7698. SEND 881618 KIT FOR BEFORE 10/9/02 PRODUCTION DATE. SEND CORD ONLY AFTER 10/9/02. DIAMETER OF CORD BECAME LARGER. CUSTOMER WILL HAVE TO DRILL HOLE 1/8" LARGER IN BOTTOM OF DOOR TO 39/64", REPLACE STRAIN RELIEF BUSHING, CABLE CLAMP AND GRILL BUSHING.
GDM-49FC	REPLACES 801723 PCN 7698. SEND 881618 KIT FOR BEFORE 10/9/02 PRODUCTION DATE. SEND CORD ONLY AFTER 10/9/02. **115V USED BETWEEN 11/9/02 - 11/1/05. DIAMETER OF CORD BECAME LARGER. CUSTOMER WILL HAVE TO DRILL HOLE 1/8" LARGER IN BOTTOM OF DOOR TO 39/64", REPLACE STRAIN RELIEF BUSHING, CABLE CLAMP AND GRILL BUSHING. CONNECT TO 801732 "Y" CORD.
GDM-49RF	REPLACES 801723 PCN 7698. SEND 881618 KIT FOR BEFORE 10/9/02 PRODUCTION DATE. SEND CORD ONLY AFTER 10/9/02. DIAMETER OF CORD BECAME LARGER. CUSTOMER WILL HAVE TO DRILL HOLE 1/8" LARGER IN BOTTOM OF DOOR TO 39/64", REPLACE STRAIN RELIEF BUSHING, CABLE CLAMP AND GRILL BUSHING. CONNECT TO 801732 "Y" CORD.
GDM-49RL	REPLACES 801723 PCN 7698. SEND 881618 KIT FOR BEFORE 10/9/02 PRODUCTION DATE. SEND CORD ONLY AFTER 10/9/02. DIAMETER OF CORD BECAME LARGER. CUSTOMER WILL HAVE TO DRILL HOLE 1/8" LARGER IN BOTTOM OF DOOR TO 39/64", REPLACE STRAIN RELIEF BUSHING, CABLE CLAMP AND GRILL BUSHING. CONNECT TO 801732 "Y" CORD.
GDM-49W-RF	REPLACES 801723 PCN 7698. SEND 881618 KIT FOR BEFORE 10/9/02 PRODUCTION DATE. SEND CORD ONLY AFTER 10/9/02. DIAMETER OF CORD BECAME LARGER. CUSTOMER WILL HAVE TO DRILL HOLE 1/8" LARGER IN BOTTOM OF DOOR TO 39/64", REPLACE STRAIN RELIEF BUSHING, CABLE CLAMP AND GRILL BUSHING. CONNECT TO 801732 "Y" CORD.
GDM-52TM	REPLACES 801723 PCN 7698. ONE USED PER DOOR, TWO PER CABINET.
GDM-72	REPLACES 801723 PCN 7698. SEND 881618 KIT FOR BEFORE 10/9/02 PRODUCTION DATE. SEND CORD ONLY AFTER 10/9/02. DIAMETER OF CORD BECAME LARGER. CUSTOMER WILL HAVE TO DRILL HOLE 1/8" LARGER IN BOTTOM OF DOOR TO 39/64", REPLACE STRAIN RELIEF BUSHING, CABLE CLAMP AND GRILL BUSHING.
GDM-72 DOLLAR GENERAL	REPLACES 801723 PCN 7698. USED BETWEEN 10/9/02 & 8/20/04.

GDM-72FC	REPLACES 801723 PCN 7698. SEND 881618 KIT FOR BEFORE 10/9/02 PRODUCTION DATE. SEND CORD ONLY AFTER 10/9/02. DIAMETER OF CORD BECAME LARGER. CUSTOMER WILL HAVE TO DRILL HOLE 1/8" LARGER IN BOTTOM OF DOOR TO 39/64", REPLACE STRAIN RELIEF BUSHING, CABLE CLAMP AND GRILL BUSHING.
GEM-49	REPLACES 801723 PCN 7698. SEND 881618 KIT FOR BEFORE 10/9/02 PRODUCTION DATE. SEND CORD ONLY AFTER 10/9/02. DIAMETER OF CORD BECAME LARGER. CUSTOMER WILL HAVE TO DRILL HOLE 1/8" LARGER IN BOTTOM OF DOOR TO 39/64", REPLACE STRAIN RELIEF BUSHING, CABLE CLAMP AND GRILL BUSHING.
GEM-49 SUBWAY	REPLACES 801723 PCN 7698.
T-19-1-G-1	REPLACES 801723 PCN 7698.
T-19G	REPLACES 801723 PCN 7698. SEND 881618 KIT FOR BEFORE 10/9/02 PRODUCTION DATE. SEND CORD ONLY AFTER 10/9/02. DIAMETER OF CORD BECAME LARGER. CUSTOMER WILL HAVE TO DRILL HOLE 1/8" LARGER IN BOTTOM OF DOOR TO 39/64", REPLACE STRAIN RELIEF BUSHING, CABLE CLAMP AND GRILL BUSHING.
T-23-1-G-1	REPLACES 801723 PCN 7698. SEND 881618 KIT FOR BEFORE 10/9/02 PRODUCTION DATE. SEND CORD ONLY AFTER 10/9/02. DIAMETER OF CORD BECAME LARGER. CUSTOMER WILL HAVE TO DRILL HOLE 1/8" LARGER IN BOTTOM OF DOOR TO 39/64", REPLACE STRAIN RELIEF BUSHING, CABLE CLAMP AND GRILL BUSHING.
T-23DT	REPLACES 801723 PCN 7698. SEND 881618 KIT FOR BEFORE 10/9/02 PRODUCTION DATE. SEND CORD ONLY AFTER 10/9/02. DIAMETER OF CORD BECAME LARGER. CUSTOMER WILL HAVE TO DRILL HOLE 1/8" LARGER IN BOTTOM OF DOOR TO 39/64", REPLACE STRAIN RELIEF BUSHING, CABLE CLAMP AND GRILL BUSHING.
T-23DT-1-G-1	REPLACES 801723 PCN 7698. SEND 881618 KIT FOR BEFORE 10/9/02 PRODUCTION DATE. SEND CORD ONLY AFTER 10/9/02. DIAMETER OF CORD BECAME LARGER. CUSTOMER WILL HAVE TO DRILL HOLE 1/8" LARGER IN BOTTOM OF DOOR TO 39/64", REPLACE STRAIN RELIEF BUSHING, CABLE CLAMP AND GRILL BUSHING.
T-23DT-G	REPLACES 801723 PCN 7698. SEND 881618 KIT FOR BEFORE 10/9/02 PRODUCTION DATE. SEND CORD ONLY AFTER 10/9/02. DIAMETER OF CORD BECAME LARGER. CUSTOMER WILL HAVE TO DRILL HOLE 1/8" LARGER IN BOTTOM OF DOOR TO 39/64", REPLACE STRAIN RELIEF BUSHING, CABLE CLAMP AND GRILL BUSHING.
T-23G	REPLACES 801723 PCN 7698. SEND 881618 KIT FOR BEFORE 10/9/02 PRODUCTION DATE. SEND CORD ONLY BETWEEN 10/9/02 AND 8/29/13. . DIAMETER OF CORD BECAME LARGER. CUSTOMER WILL HAVE TO DRILL HOLE 1/8" LARGER IN BOTTOM OF DOOR TO 39/64", REPLACE STRAIN RELIEF BUSHING, CABLE CLAMP AND GRILL BUSHING. USED BEFORE 6/25/13 PER PCN 6731.

T-23G-PT-LD MCD1	REPLACES 801723 PCN 7698.
T-23G-RL	REPLACES 801723 PCN 7698. SEND 881618 KIT FOR BEFORE 10/9/02 PRODUCTION DATE. SEND CORD ONLY AFTER 10/9/02. DIAMETER OF CORD BECAME LARGER. CUSTOMER WILL HAVE TO DRILL HOLE 1/8" LARGER IN BOTTOM OF DOOR TO 39/64", REPLACE STRAIN RELIEF BUSHING, CABLE CLAMP AND GRILL BUSHING.
T-35G	REPLACES 801723 PCN 7698. SEND 881618 KIT FOR BEFORE 10/9/02 PRODUCTION DATE. SEND CORD ONLY AFTER 10/9/02. DIAMETER OF CORD BECAME LARGER. CUSTOMER WILL HAVE TO DRILL HOLE 1/8" LARGER IN BOTTOM OF DOOR TO 39/64", REPLACE STRAIN RELIEF BUSHING, CABLE CLAMP AND GRILL BUSHING.
T-49-2-G-2	REPLACES 801723 PCN 7698.
T-49DT-G	REPLACES 801723 PCN 7698. SEND 881618 KIT FOR BEFORE 10/9/02 PRODUCTION DATE. SEND CORD ONLY AFTER 10/9/02. DIAMETER OF CORD BECAME LARGER. CUSTOMER WILL HAVE TO DRILL HOLE 1/8" LARGER IN BOTTOM OF DOOR TO 39/64", REPLACE STRAIN RELIEF BUSHING, CABLE CLAMP AND GRILL BUSHING.
T-49G	REPLACES 801723 PCN 7698. USED BEFORE 8/29/13 PER PCN 6730. SEND 881618 KIT FOR BEFORE 10/9/02 PRODUCTION DATE. SEND CORD ONLY AFTER 10/9/02. DIAMETER OF CORD BECAME LARGER. CUSTOMER WILL HAVE TO DRILL HOLE 1/8" LARGER IN BOTTOM OF DOOR TO 39/64", REPLACE STRAIN RELIEF BUSHING, CABLE CLAMP AND GRILL BUSHING.
T-49G-4	REPLACES 801723 PCN 7698. SEND 881618 KIT FOR BEFORE 10/9/02 PRODUCTION DATE. SEND CORD ONLY AFTER 10/9/02. DIAMETER OF CORD BECAME LARGER. CUSTOMER WILL HAVE TO DRILL HOLE 1/8" LARGER IN BOTTOM OF DOOR TO 39/64", REPLACE STRAIN RELIEF BUSHING, CABLE CLAMP AND GRILL BUSHING.
T-49G-PT	REPLACES 801723 PCN 7698. SEND 912009 KIT FOR BEFORE 10/9/02 PRODUCTION DATE. SEND CORD ONLY AFTER 10/9/02. DIAMETER OF CORD BECAME LARGER. CUSTOMER WILL HAVE TO DRILL HOLE 1/8" LARGER IN BOTTOM OF DOOR TO 39/64", REPLACE STRAIN RELIEF BUSHING, CABLE CLAMP AND GRILL BUSHING.
T-49G-RL	REPLACES 801723 PCN 7698. SEND 881618 KIT FOR BEFORE 10/9/02 PRODUCTION DATE. SEND CORD ONLY AFTER 10/9/02. DIAMETER OF CORD BECAME LARGER. CUSTOMER WILL HAVE TO DRILL HOLE 1/8" LARGER IN BOTTOM OF DOOR TO 39/64", REPLACE STRAIN RELIEF BUSHING, CABLE CLAMP AND GRILL BUSHING.
T-72-3-G-3	REPLACES 801723 PCN 7698. SEND 881618 KIT FOR BEFORE 10/9/02 PRODUCTION DATE. SEND CORD ONLY AFTER 10/9/02. DIAMETER OF CORD BECAME LARGER. CUSTOMER WILL HAVE TO DRILL HOLE 1/8" LARGER IN BOTTOM OF DOOR TO 39/64", REPLACE STRAIN RELIEF BUSHING, CABLE CLAMP AND GRILL BUSHING.

T-72G	REPLACES 801723 PCN 7698. SEND 881618 KIT FOR BEFORE 10/9/02 PRODUCTION DATE. SEND CORD ONLY AFTER 10/9/02. DIAMETER OF CORD BECAME LARGER. CUSTOMER WILL HAVE TO DRILL HOLE 1/8" LARGER IN BOTTOM OF DOOR TO 39/64", REPLACE STRAIN RELIEF BUSHING, CABLE CLAMP AND GRILL BUSHING.
T-72G-6	REPLACES 801723 PCN 7698. SEND 881618 KIT FOR BEFORE 10/9/02 PRODUCTION DATE. SEND CORD ONLY AFTER 10/9/02. DIAMETER OF CORD BECAME LARGER. CUSTOMER WILL HAVE TO DRILL HOLE 1/8" LARGER IN BOTTOM OF DOOR TO 39/64", REPLACE STRAIN RELIEF BUSHING, CABLE CLAMP AND GRILL BUSHING.
TA1R-1G	REPLACES 801723 PCN 7698.
TA1R-1HG/1HS	REPLACES 801723 PCN 7698.
TA1R-2HG	REPLACES 801723 PCN 7698.
TA1RPT-1G-1G	REPLACES 801723 PCN 7698.
TA1RPT-1G-1S	REPLACES 801723 PCN 7698.
TA1RPT-1HG/1HS-1G	REPLACES 801723 PCN 7698.
TA1RPT-1HG/1HS-1S	REPLACES 801723 PCN 7698.
TA1RPT-1S-1G	REPLACES 801723 PCN 7698.
TA1RPT-2HG-1G	REPLACES 801723 PCN 7698.
TA1RPT-2HG-1S	REPLACES 801723 PCN 7698.
TA1RPT-2HS-1G	REPLACES 801723 PCN 7698.
TA2R-2G	REPLACES 801723 PCN 7698.
TA2R-2HG/2HS	REPLACES 801723 PCN 7698.
TA2R-4HG	REPLACES 801723 PCN 7698.
TA2RPT-2G-2G	REPLACES 801723 PCN 7698.
TA2RPT-2G-2S	REPLACES 801723 PCN 7698.
TA2RPT-2HG/2HS-2G	REPLACES 801723 PCN 7698.
TA2RPT-2HG/2HS-2S	REPLACES 801723 PCN 7698.
TA2RPT-2S-2G	REPLACES 801723 PCN 7698.
TA2RPT-4HG-2G	REPLACES 801723 PCN 7698.
TA2RPT-4HG-2S	REPLACES 801723 PCN 7698.
TA2RPT-4HG-4HG	REPLACES 801723 PCN 7698.
TA2RPT-4HG-4HS	REPLACES 801723 PCN 7698.
TA2RPT-4HS-2G	REPLACES 801723 PCN 7698.
TA3R-3G	REPLACES 801723 PCN 7698.

TC-23G	REPLACES 801723 PCN 7698. SEND 881618 KIT FOR BEFORE 10/9/02 PRODUCTION DATE. SEND CORD ONLY AFTER 10/9/02. DIAMETER OF CORD BECAME LARGER. CUSTOMER WILL HAVE TO DRILL HOLE 1/8" LARGER IN BOTTOM OF DOOR TO 39/64", REPLACE STRAIN RELIEF BUSHING, CABLE CLAMP AND GRILL BUSHING.
TC-49G	REPLACES 801723 PCN 7698. SEND 881618 KIT FOR BEFORE 10/9/02 PRODUCTION DATE. SEND CORD ONLY AFTER 10/9/02. DIAMETER OF CORD BECAME LARGER. CUSTOMER WILL HAVE TO DRILL HOLE 1/8" LARGER IN BOTTOM OF DOOR TO 39/64", REPLACE STRAIN RELIEF BUSHING, CABLE CLAMP AND GRILL BUSHING.
TG1R-1G	REPLACES 801723 PCN 7698.
TG1R-1HG/1HS	REPLACES 801723 PCN 7698.
TG1R-2HG	REPLACES 801723 PCN 7698.
TG1RPT-1G-1G	REPLACES 801723 PCN 7698.
TG1RPT-1G-1S	REPLACES 801723 PCN 7698.
TG1RPT-1G-2HS	REPLACES 801723 PCN 7698.
TG1RPT-1HG/1HS-1G	REPLACES 801723 PCN 7698.
TG1RPT-1HG/1HS-1S	REPLACES 801723 PCN 7698.
TG1RPT-1S-1G	REPLACES 801723 PCN 7698.
TG1RPT-2HG/1S	REPLACES 801723 PCN 7698.
TG1RPT-2HG-1G	REPLACES 801723 PCN 7698.
TG1RPT-2HS-1G	REPLACES 801723 PCN 7698.
TG2R-2G	REPLACES 801723 PCN 7698.
TG2R-2HG/2HS	REPLACES 801723 PCN 7698.
TG2R-4HG	REPLACES 801723 PCN 7698.
TG2RPT-2G-2G	REPLACES 801723 PCN 7698.
TG2RPT-2G-2S	REPLACES 801723 PCN 7698.
TG2RPT-2HG/2HS-2G	REPLACES 801723 PCN 7698.
TG2RPT-2HG/2HS-2S	REPLACES 801723 PCN 7698.
TG2RPT-2S-2G	REPLACES 801723 PCN 7698.
TG2RPT-4HG-2G	REPLACES 801723 PCN 7698.
TG2RPT-4HG-2S	REPLACES 801723 PCN 7698.
TG2RPT-4HG-4HG	REPLACES 801723 PCN 7698.
TG2RPT-4HS-2G	REPLACES 801723 PCN 7698.
TG3R-3G	REPLACES 801723 PCN 7698.
TM-24G	REPLACES 801723 PCN 7698.

TM-24G-2	REPLACES 801723 PCN 7698.
TM-52G	REPLACES 801723 PCN 7698.
TM-52G-4	REPLACES 801723 PCN 7698.
TM-74G	REPLACES 801723 PCN 7698.
TR1R-1G	REPLACES 801723 PCN 7698.
TR1R-1HG/1HS	REPLACES 801723 PCN 7698.
TR1R-2HG	REPLACES 801723 PCN 7698.
TR1RPT-1G-1G	REPLACES 801723 PCN 7698.
TR1RPT-1G-1HG/1HS	REPLACES 801723 PCN 7698.
TR1RPT-1G-1S	REPLACES 801723 PCN 7698.
TR1RPT-1G-2HG	REPLACES 801723 PCN 7698.
TR1RPT-1G-2HS	REPLACES 801723 PCN 7698.
TR1RPT-1HG/1HS-1G	REPLACES 801723 PCN 7698.
TR1RPT-1HG/1HS-1S	REPLACES 801723 PCN 7698.
TR1RPT-1HG/1HS-2HG	REPLACES 801723 PCN 7698.
TR1RPT-1HG/1HS-2HS	REPLACES 801723 PCN 7698.
TR1RPT-1HGLH/1HSLH-1HG/1HS	REPLACES 801723 PCN 7698.
TR1RPT-1S-1G	REPLACES 801723 PCN 7698.
TR1RPT-1S-1HG/1HS	REPLACES 801723 PCN 7698.
TR1RPT-1S-2HG	REPLACES 801723 PCN 7698.
TR1RPT-2HG-1G	REPLACES 801723 PCN 7698.
TR1RPT-2HG-1HG/1HS	REPLACES 801723 PCN 7698.
TR1RPT-2HG-1S	REPLACES 801723 PCN 7698.
TR1RPT-2HG-2HG	REPLACES 801723 PCN 7698.
TR1RPT-2HG-2HS	REPLACES 801723 PCN 7698.
TR1RPT-2HS-1G	REPLACES 801723 PCN 7698.
TR1RPT-2HS-1HG/1HS	REPLACES 801723 PCN 7698.
TR1RPT-2HS-2HG	REPLACES 801723 PCN 7698.
TR2R-2G	REPLACES 801723 PCN 7698.
TR2R-2HG/2HS	REPLACES 801723 PCN 7698.
TR2R-4HG	REPLACES 801723 PCN 7698.
TR2RPT-1G/1S-1G/1S	REPLACES 801723 PCN 7698.
TR2RPT-1G/1S-1G/2HS	REPLACES 801723 PCN 7698.
TR2RPT-1G/1S-2G	REPLACES 801723 PCN 7698.

TR2RPT-1G/1S-2HG/1S	REPLACES 801723 PCN 7698.
TR2RPT-1G/1S-2HG/2HS	REPLACES 801723 PCN 7698.
TR2RPT-1G/1S-2S	REPLACES 801723 PCN 7698.
TR2RPT-1G/1S-4HG	REPLACES 801723 PCN 7698.
TR2RPT-1G/1S-4HS	REPLACES 801723 PCN 7698.
TR2RPT-1G/2HG-2HG/2HS	REPLACES 801723 PCN 7698.
TR2RPT-1G/2HS-1G/1S	REPLACES 801723 PCN 7698.
TR2RPT-1G/2HS-1G/2HS	REPLACES 801723 PCN 7698.
TR2RPT-1G/2HS-2HG/1S	REPLACES 801723 PCN 7698.
TR2RPT-1G/2HS-2S	REPLACES 801723 PCN 7698.
TR2RPT-1G/2HS-4HG	REPLACES 801723 PCN 7698.
TR2RPT-1G/2HS-4HS	REPLACES 801723 PCN 7698.
TR2RPT-2G-1G/1S	REPLACES 801723 PCN 7698.
TR2RPT-2G-1G/2HS	REPLACES 801723 PCN 7698.
TR2RPT-2G-2G	REPLACES 801723 PCN 7698.
TR2RPT-2G-2HG/1S	REPLACES 801723 PCN 7698.
TR2RPT-2G-2HG/2HS	REPLACES 801723 PCN 7698.
TR2RPT-2G-2S	REPLACES 801723 PCN 7698.
TR2RPT-2G-4HG	REPLACES 801723 PCN 7698.
TR2RPT-2G-4HS	REPLACES 801723 PCN 7698.
TR2RPT-2HG/1S-1G/1S	REPLACES 801723 PCN 7698.
TR2RPT-2HG/1S-1G/2HS	REPLACES 801723 PCN 7698.
TR2RPT-2HG/1S-2G	REPLACES 801723 PCN 7698.
TR2RPT-2HG/1S-2HG/1S	REPLACES 801723 PCN 7698.
TR2RPT-2HG/1S-2HG/2HS	REPLACES 801723 PCN 7698.
TR2RPT-2HG/1S-2S	REPLACES 801723 PCN 7698.
TR2RPT-2HG/1S-4HG	REPLACES 801723 PCN 7698.
TR2RPT-2HG/1S-4HS	REPLACES 801723 PCN 7698.
TR2RPT-2HG/2HS-1G/1S	REPLACES 801723 PCN 7698.
TR2RPT-2HG/2HS-1G/2HS	REPLACES 801723 PCN 7698.
TR2RPT-2HG/2HS-2G	REPLACES 801723 PCN 7698.
TR2RPT-2HG/2HS-2HG/1S	REPLACES 801723 PCN 7698.
TR2RPT-2HG/2HS-2HG/2HS	REPLACES 801723 PCN 7698.
TR2RPT-2HG/2HS-2S	REPLACES 801723 PCN 7698.

TR2RPT-2HG/2HS-4HG	REPLACES 801723 PCN 7698.
TR2RPT-2HG/2HS-4HS	REPLACES 801723 PCN 7698.
TR2RPT-2S-1G/1S	REPLACES 801723 PCN 7698.
TR2RPT-2S-1G/2HS	REPLACES 801723 PCN 7698.
TR2RPT-2S-2G	REPLACES 801723 PCN 7698.
TR2RPT-2S-2HG/1S	REPLACES 801723 PCN 7698.
TR2RPT-2S-2HG/2HS	REPLACES 801723 PCN 7698.
TR2RPT-2S-4HG	REPLACES 801723 PCN 7698.
TR2RPT-4HG-1G/1S	REPLACES 801723 PCN 7698.
TR2RPT-4HG-1G/2HS	REPLACES 801723 PCN 7698.
TR2RPT-4HG-2G	REPLACES 801723 PCN 7698.
TR2RPT-4HG-2HG/1S	REPLACES 801723 PCN 7698.
TR2RPT-4HG-2HG/2HS	REPLACES 801723 PCN 7698.
TR2RPT-4HG-2S	REPLACES 801723 PCN 7698.
TR2RPT-4HG-4HG	REPLACES 801723 PCN 7698.
TR2RPT-4HG-4HS	REPLACES 801723 PCN 7698.
TR2RPT-4HS-1G/1S	REPLACES 801723 PCN 7698.
TR2RPT-4HS-1G/2HS	REPLACES 801723 PCN 7698.
TR2RPT-4HS-2G	REPLACES 801723 PCN 7698.
TR2RPT-4HS-2HG/1S	REPLACES 801723 PCN 7698.
TR2RPT-4HS-2HG/2HS	REPLACES 801723 PCN 7698.
TR2RPT-4HS-4HG	REPLACES 801723 PCN 7698.
TR-31-1-G-1	REPLACES 801723 PCN 7698.
TR-31-2-G-2	REPLACES 801723 PCN 7698.
TR-31G	REPLACES 801723 PCN 7698.
TR-31G-2	REPLACES 801723 PCN 7698.
TR3R-3G	REPLACES 801723 PCN 7698.
TR-56-2-G-2	REPLACES 801723 PCN 7698.
TR-56G	REPLACES 801723 PCN 7698.
TR-56G-4	REPLACES 801723 PCN 7698.
TR-85-3-G-3	REPLACES 801723 PCN 7698.
TR-85G	REPLACES 801723 PCN 7698.
TR-85G-6	REPLACES 801723 PCN 7698.

TS-23-1-G-1	REPLACES 801723 PCN 7698. SEND 881618 KIT FOR BEFORE 10/9/02 PRODUCTION DATE. SEND CORD ONLY AFTER 10/9/02. DIAMETER OF CORD BECAME LARGER. CUSTOMER WILL HAVE TO DRILL HOLE 1/8" LARGER IN BOTTOM OF DOOR TO 39/64", REPLACE STRAIN RELIEF BUSHING, CABLE CLAMP AND GRILL BUSHING.
TS-23G	REPLACES 801723 PCN 7698. SEND 881618 KIT FOR BEFORE 10/9/02 PRODUCTION DATE. SEND CORD ONLY BETWEEN 10/9/02 AND 8/29/13. DIAMETER OF CORD BECAME LARGER. CUSTOMER WILL HAVE TO DRILL HOLE 1/8" LARGER IN BOTTOM OF DOOR TO 39/64", REPLACE STRAIN RELIEF BUSHING, CABLE CLAMP AND GRILL BUSHING. USED BEFORE 6/25/13 PER PCN 6731.
TS-23G-2	REPLACES 801723 PCN 7698. SEND 881618 KIT FOR BEFORE 10/9/02 PRODUCTION DATE. SEND CORD ONLY AFTER 10/9/02. DIAMETER OF CORD BECAME LARGER. CUSTOMER WILL HAVE TO DRILL HOLE 1/8" LARGER IN BOTTOM OF DOOR TO 39/64", REPLACE STRAIN RELIEF BUSHING, CABLE CLAMP AND GRILL BUSHING.
TS-28-2-G-2PT	REPLACES 801723 PCN 7698. SEND 881618 KIT FOR BEFORE 10/9/02 PRODUCTION DATE. SEND CORD ONLY AFTER 10/9/02. DIAMETER OF CORD BECAME LARGER. CUSTOMER WILL HAVE TO DRILL HOLE 1/8" LARGER IN BOTTOM OF DOOR TO 39/64", REPLACE STRAIN RELIEF BUSHING, CABLE CLAMP AND GRILL BUSHING.
TS-28G-2	REPLACES 801723 PCN 7698. SEND 881618 KIT FOR BEFORE 10/9/02 PRODUCTION DATE. SEND CORD ONLY AFTER 10/9/02. DIAMETER OF CORD BECAME LARGER. CUSTOMER WILL HAVE TO DRILL HOLE 1/8" LARGER IN BOTTOM OF DOOR TO 39/64", REPLACE STRAIN RELIEF BUSHING, CABLE CLAMP AND GRILL BUSHING.
TS-28G-2PT	REPLACES 801723 PCN 7698. SEND 881618 KIT FOR BEFORE 10/9/02 PRODUCTION DATE. SEND CORD ONLY AFTER 10/9/02. DIAMETER OF CORD BECAME LARGER. CUSTOMER WILL HAVE TO DRILL HOLE 1/8" LARGER IN BOTTOM OF DOOR TO 39/64", REPLACE STRAIN RELIEF BUSHING, CABLE CLAMP AND GRILL BUSHING.
TS-28G-PT	REPLACES 801723 PCN 7698. SEND 881618 KIT FOR BEFORE 10/9/02 PRODUCTION DATE. SEND CORD ONLY AFTER 10/9/02. DIAMETER OF CORD BECAME LARGER. CUSTOMER WILL HAVE TO DRILL HOLE 1/8" LARGER IN BOTTOM OF DOOR TO 39/64", REPLACE STRAIN RELIEF BUSHING, CABLE CLAMP AND GRILL BUSHING.
TS-28G-RL	REPLACES 801723 PCN 7698. SEND 881618 KIT FOR BEFORE 10/9/02 PRODUCTION DATE. SEND CORD ONLY AFTER 10/9/02. DIAMETER OF CORD BECAME LARGER. CUSTOMER WILL HAVE TO DRILL HOLE 1/8" LARGER IN BOTTOM OF DOOR TO 39/64", REPLACE STRAIN RELIEF BUSHING, CABLE CLAMP AND GRILL BUSHING.

TS-35G	REPLACES 801723 PCN 7698. SEND 881618 KIT FOR BEFORE 10/9/02 PRODUCTION DATE. SEND CORD ONLY AFTER 10/9/02. DIAMETER OF CORD BECAME LARGER. CUSTOMER WILL HAVE TO DRILL HOLE 1/8" LARGER IN BOTTOM OF DOOR TO 39/64", REPLACE STRAIN RELIEF BUSHING, CABLE CLAMP AND GRILL BUSHING.
TS-49-2-G-2	REPLACES 801723 PCN 7698. SEND 881618 KIT FOR BEFORE 10/9/02 PRODUCTION DATE. SEND CORD ONLY AFTER 10/9/02. DIAMETER OF CORD BECAME LARGER. CUSTOMER WILL HAVE TO DRILL HOLE 1/8" LARGER IN BOTTOM OF DOOR TO 39/64", REPLACE STRAIN RELIEF BUSHING, CABLE CLAMP AND GRILL BUSHING.
TS-49G	REPLACES 801723 PCN 7698. USED BEFORE 8/29/13 PER PCN 6730. SEND 881618 KIT FOR BEFORE 10/9/02 PRODUCTION DATE. SEND CORD ONLY AFTER 10/9/02. DIAMETER OF CORD BECAME LARGER. CUSTOMER WILL HAVE TO DRILL HOLE 1/8" LARGER IN BOTTOM OF DOOR TO 39/64", REPLACE STRAIN RELIEF BUSHING, CABLE CLAMP AND GRILL BUSHING.
TS-49G-4	REPLACES 801723 PCN 7698. SEND 881618 KIT FOR BEFORE 10/9/02 PRODUCTION DATE. SEND CORD ONLY AFTER 10/9/02. DIAMETER OF CORD BECAME LARGER. CUSTOMER WILL HAVE TO DRILL HOLE 1/8" LARGER IN BOTTOM OF DOOR TO 39/64", REPLACE STRAIN RELIEF BUSHING, CABLE CLAMP AND GRILL BUSHING.
TS-53-4-G-4PT	REPLACES 801723 PCN 7698. SEND 881618 KIT FOR BEFORE 10/9/02 PRODUCTION DATE. SEND CORD ONLY AFTER 10/9/02. DIAMETER OF CORD BECAME LARGER. CUSTOMER WILL HAVE TO DRILL HOLE 1/8" LARGER IN BOTTOM OF DOOR TO 39/64", REPLACE STRAIN RELIEF BUSHING, CABLE CLAMP AND GRILL BUSHING.
TS-53G-4	REPLACES 801723 PCN 7698. SEND 881618 KIT FOR BEFORE 10/9/02 PRODUCTION DATE. SEND CORD ONLY AFTER 10/9/02. DIAMETER OF CORD BECAME LARGER. CUSTOMER WILL HAVE TO DRILL HOLE 1/8" LARGER IN BOTTOM OF DOOR TO 39/64", REPLACE STRAIN RELIEF BUSHING, CABLE CLAMP AND GRILL BUSHING.
TS-53G-PT	REPLACES 801723 PCN 7698. SEND 881618 KIT FOR BEFORE 10/9/02 PRODUCTION DATE. SEND CORD ONLY AFTER 10/9/02. DIAMETER OF CORD BECAME LARGER. CUSTOMER WILL HAVE TO DRILL HOLE 1/8" LARGER IN BOTTOM OF DOOR TO 39/64", REPLACE STRAIN RELIEF BUSHING, CABLE CLAMP AND GRILL BUSHING.
TS-53G-PT-2G-2S	REPLACES 801723 PCN 7698. SEND 881618 KIT FOR BEFORE 10/9/02 PRODUCTION DATE. SEND CORD ONLY AFTER 10/9/02. DIAMETER OF CORD BECAME LARGER. CUSTOMER WILL HAVE TO DRILL HOLE 1/8" LARGER IN BOTTOM OF DOOR TO 39/64", REPLACE STRAIN RELIEF BUSHING, CABLE CLAMP AND GRILL BUSHING.

TS-53G-RL	REPLACES 801723 PCN 7698. SEND 881618 KIT FOR BEFORE 10/9/02 PRODUCTION DATE. SEND CORD ONLY AFTER 10/9/02. DIAMETER OF CORD BECAME LARGER. CUSTOMER WILL HAVE TO DRILL HOLE 1/8" LARGER IN BOTTOM OF DOOR TO 39/64", REPLACE STRAIN RELIEF BUSHING, CABLE CLAMP AND GRILL BUSHING.
TS-72-3-G-3	REPLACES 801723 PCN 7698. SEND 881618 KIT FOR BEFORE 10/9/02 PRODUCTION DATE. SEND CORD ONLY AFTER 10/9/02. DIAMETER OF CORD BECAME LARGER. CUSTOMER WILL HAVE TO DRILL HOLE 1/8" LARGER IN BOTTOM OF DOOR TO 39/64", REPLACE STRAIN RELIEF BUSHING, CABLE CLAMP AND GRILL BUSHING.
TS-72-6	REPLACES 801723 PCN 7698. SEND 881618 KIT FOR BEFORE 10/9/02 PRODUCTION DATE. SEND CORD ONLY AFTER 10/9/02. DIAMETER OF CORD BECAME LARGER. CUSTOMER WILL HAVE TO DRILL HOLE 1/8" LARGER IN BOTTOM OF DOOR TO 39/64", REPLACE STRAIN RELIEF BUSHING, CABLE CLAMP AND GRILL BUSHING.
TVM-400	REPLACES 801723 PCN 7698.