

Trestle Table Bases

ASSEMBLY INSTRUCTIONS



LANCASTER™
TABLE & SEATING

INDUSTRIAL Series



CAUTION

Due to the weight of these items, assembly should be performed by two people to prevent injury and/or damage.


Use caution when lowering base into place to avoid pinching fingers under the weight.

CONTENTS:

- A** (4) Leg
- B** (2) Iron Side Bottom Brace
- C** (2) Iron Side Top Brace
- D** (1) Connector Bar
- E** (2) Brace Support
- F** (1) Table Top


TOOLS:

- G** (2) Allen Wrench
- (1) Phillips Head Screwdriver (Not Included)
- (1) Drill (Not Included)



HARDWARE:

- AA** (4) Adjustable Footpad
- BB** (44) Round Cap Wire Screw
- CC** (8) Button Nut Screw
- DD** (8) Button Nut Screw Cap



- EE** (2) Combined Screw



- FF** (2) Flat Washer



- GG** (2) Locking Washer



Trestle Table Bases

ASSEMBLY INSTRUCTIONS




LANCASTER™
TABLE & SEATING

INDUSTRIAL Series


STEP 1

Gather iron side top braces (C) and brace supports (E), 2 pieces each. Place them upside down on the floor as shown.




STEP 2

Secure both parts at pre-drilled holes using 2 button nut screw caps (DD) from the brace support (E) and 2 button nut screws (CC) from the opposite side. Use both allen wrenches (G) simultaneously to secure. Repeat for second pair.



STEP 3

Place the connector bar (D) on top of the brace supports (E), lining up the pre-drilled holes. Secure the brace supports (E) to the connector bar (D) using 1 combined screw (EE), 1 flat washer (FF), and 1 locking washer (gg) from the brace support (E) side. Repeat on opposite end.



Trestle Table Bases

ASSEMBLY INSTRUCTIONS




LANCASTER™
TABLE & SEATING

INDUSTRIAL Series


STEP 4

Place table legs (A) into the iron side top braces (C), ensuring the foot end of each leg is level. Then, place iron side bottom brace (B) down the table legs (A) to meet the connector bar (D) at the pre-drilled holes.




STEP 5

Secure iron side bottom braces (B) to connector bar (D) using 2 button nut screws (CC) from the outside and 2 button nut screw caps (DD) from the opposite side. Secure using both allen wrenches (G) simultaneously. Repeat for other end.




STEP 6

Secure iron side bottom brace (B) to table legs (A) by using round cap wire screws (BB) in the pre-drilled holes (4 per leg). If using a drill, you can drill pilot holes before installing the screws.



STEP 7

Secure iron side top brace (C) to table legs (A) by using round cap wire screws (BB) in the pre-drilled holes (4 per leg). If using a drill, you can drill pilot holes before installing the screws.



Trestle Table Bases

ASSEMBLY INSTRUCTIONS




LANCASTER™
TABLE & SEATING

INDUSTRIAL Series


STEP 8

Place and secure adjustable footpads (AA) to the bottom of each table leg (A).



STEP 9

Turn the base right side up. Secure iron side top braces (C) to table legs (A) using a round cap wire screw (BB) in each.



STEP 10

Place the table top (F) onto the iron side top braces (C). Secure using round cap wire screws (BB) from the underside (4 per end).

