



Walk-In Beer Cave Cooler Shelving

Assembly Instructions




Part Identification


Frame Upright




Shelf




Bottom Shelf




Starter Cross Bar




Cross Bar




Frame Assembly**Fig. 1**


- Line the starter cross bar fins with the bottom two slots on the frame upright.

**Fig. 2**

- Press the crossbar into the upright frame slots.

**Fig. 3**

- Pull the crossbar down to lock into place.

**Fig. 4**

- Repeat figures 1–4 to install the second upright.

Shelf Locations




Fig. 5

- Repeat steps 1–3 to attach the rear starter crossbar onto the back bars of the frame upright.




Fig. 6

- Place the bottom shelf into the assembly.





Fig. 7

- Determine the shelf spacing and pitch for your application


0 Degree Shelf Angle



- Align all three cross bars so that they are at the same height.

Shelf Locations

6.5 Degree Shelf Angle




Front

Middle

Back

- The crossbars will be spaced up in **ONE** level increments.

13 Degree Shelf Angle



Front

Middle

Back

- The crossbars will be spaced up in **TWO** level increments.




Fig. 8

- Place the shelves onto the crossbars.




Fig. 9

- Add on additional shelving as needed.



Wanzl worldwide

- **Head Office**
- Subsidiaries
- Partners

WANZL NORTH AMERICA

700 Technibilt Drive
PO Box 310
Newton, NC 28658

Phone +1 800-351-2278

Fax +1 800-968-8934

customerservice.us.new@wanzl.com

www.wanzl.com/na

GERMANY

Wanzl GmbH & Co. KGaA
Rudolf-Wanzl-Straße 4
89340 Leipheim

Phone +49 (0) 82 21 / 7 29-0

Fax +49 (0) 82 21 / 7 29-1000

info@wanzl.com

www.wanzl.com