

WASHING INSTRUCTIONS: Down Products

MACHINE WASH



Wash cold between 15°C & 25°C (Between 60F & 80F)

BLEACH



Do not use chlorine bleach

IRON



Do not Iron

DRY



Tumble dry low (not exceeding 55°C / 130F)

GENERAL TIPS

Always shake out down products before laundering

Keep products clear of the floor - floor stains are difficult to remove

One of the most common laundering problems is machine overloading. It should be 75% filled.

Front Loading Large Capacity Washer and Dryer recommended

WASHING

Do not mix products / material to prevent cross-contamination & products damage.

Wash and Rinse in cold water

Mild detergent

Gentle Cycle

Do not use chlorine bleach

DRYING

Always check to see if a treated stain was removed after laundering and before drying.

The heat will set the stain

Tumble dry at low setting (not exceeding 55°C / 131F)

Do not overfill the dryer or run it longer than necessary. Over drying can result in scorching, loss of brightness and a harsh hand feel.

Maintain efficient door seals and clean lint filters in the dryer

Always use a cool down stage at the end of drying to prevent creasing

Do not use fabric softener

Do not dry clean, bleach, iron or steam.