

DANGER: HARMFUL IF SWALLOWED. CONTACT WITH SKIN OR EYES CAN CAUSE SEVERE BURNS. DO NOT MIX WITH ANYTHING BUT WATER.

DESCRIPTION

Arctic Ice Machine Cleaner is specifically designed for removal of mineral build-ups which can lead to bacterial contamination in ice machine equipment protecting, your nickel plated evaporator in ice machines.

DIRECTIONS

The equipment should be cleaned with Noble Chemical Arctic ice machine cleaner followed by a rinse. A solution of 2 oz. per gallon of Arctic Ice Machine Cleaner should then be circulated and brushed on all surfaces. Allow to soak for additional 10 minutes, followed by a thorough fresh water rinse.

FIRST AID

EXTERNAL: Immediately flush skin with plenty of cool running water for at least 15 minutes.

EYES: Immediately flush with plenty of cool running water for at least 15 minutes.

INTERNAL: If swallowed, DO NOT induce vomiting. Immediately drink large quantities of raw egg, milk or milk of magnesia, then drink large quantity of water. Follow with vegetable, olive or mineral oil.

GET MEDICAL ATTENTION IMMEDIATELY!

Contains: Phosphoric Acid (7664-38-2), Alkylaryl Polyether Alcohol (N/A),

NJTSR# 39210900-5116P, Dye (N/A)

HMIS Hazardous Materials I.D. System

Health 2 Flammability 0 Reactivity 2

Solely for Industrial Use

Distributed by

NOBLE CHEMICAL

FOR CUSTOMER SERVICE CALL: 1-888-256-6400