







Lime-B-Gone

Stainless Steel Brightener Acid Cleaner

Delimes • Dissolves • Destains

Net Contents: 1 Gallon - 4/CS

DIRECTIONS FOR FOOD SERVICE EQUIPMENT DE-LIMING DISH MACHINES: Fill tank 2-3 in. below overflow level, turn tank heaters on. Add 2-4 oz. and allow machine to run until lime scale dissapears. Apply full strength to areas where spray does not reach. Where lime buildup is heavy, scrape excess deposits. Drain tank and refill with fresh water. Run machine for 5 min, and drain. De-lime as necessary to prevent heavy build-ups from occurring. DE-LIMING STEAM TABLES: Brush or spray full strength on interior surfaces. Let stand 10 min., then fill with water. Turn on heat, bring to operating temperature, and let stand for 10 min. Brush or scrape off remaining deposits. Drain and flush throughly with clean water. CLEANING STAINLESS STEEL & ALUMINUM EQUIPMENT: Apply solution of 3 oz. per gal, of hot water with saturated sponge or cloth. Rinse with clean water and wipe dry. CLEANING UTENSILS: Soak utensils in solution of 3 oz. per gal. of hot water until bright. Rinse throughly in clean water and drain dry. DESCALING COFFEE URNS: Fill water jacket of urn with hot water and add 1 oz. per gal. of water. Heat and let stand for 15 min. Drain and rinse thoroughly with clean water.

DANGER

HAZARD STATEMENTS

Harmful if swallowed.

Causes severe skin burns and eve damage

PRECAUTIONARY STATEMENTS

Prevention: Wash face, hands and any exposed skin thoroughly after handling. Do not eat, drink or smoke when using this product. Do not breathe dust/fume/gas/mist/vapors/spray. Wear protective gloves/protective clothing/eve protection/face protection. **General** Advice: Immediately call a POISON CENTER or doctor/physician. Eves: IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. Immediately call a POISON CENTER or doctor/physician. Skin: IF ON SKIN (or hair): Take off immediately all contaminated clothing. Rinse skin with water/shower. Wash contaminated clothing before reuse. Inhalation: IF INHALED: Remove victim to fresh air and keep at rest in a position comfortable for breathing. Ingestion: IF SWALLOWED: Call a POISON CENTER or doctor/physician if you feel unwell. Rinse mouth. DO NOT induce vomiting. Fire: None. Spills and Leaks: None, Storage: Store locked up. Disposal: Dispose of contents/container to an approved waste disposal plant.

INGREDIENTS: MURIATIC ACID (CAS# 7647-01-0). PHOSPHORIC ACID (CAS# 7664-38-2). WATER (CAS# 7732-18-5). MODIFIED ALKYL ARYL POLYETHER (CAS# 60864-33-7), COLORANT



Distributed by: Noble Chemical, Inc. 2205 Old Philadelphia Pike Lancaster, PA 17602

For customer service or for more ingredient information visit: www.NobleChemical.com or call: 1-888-256-6400



EACH 999LIMEBGONE









