

Model-Specific Compatibility Notes [09/11/2015]:

TSSU-48-12M-B: Note, pre 1998 hoods are no longer available.

TSSU-36-12M-B: Note, pre 1998 hoods are no longer available.

TSSU-27-12M: Note, pre 1998 hoods are no longer available.

TSSU-48-12M: Note, pre 1998 hoods are no longer available.

TSSU-36-12M: Note, pre 1998 hoods are no longer available.

TSSU-27-12M-C: Note, pre 1998 hoods are no longer available.

TSSU-27-12M-B: Note, pre 1998 hoods are no longer available.

TSSU-27-12MB-LP: Note, pre 1998 hoods are no longer available.

TSSU-27-12MC-LP: Note, pre 1998 hoods are no longer available.

TSSU-36-12MB-LP: Note, pre 1998 hoods are no longer available.

TSSU-48-12MB-LP: Note, pre 1998 hoods are no longer available.

TSSU-72-30M-B-ST: Used standard after 11/20/05 production date although the 15 pan configuration is still an option. check workorder to see if 15 pan configuration noted.

TSSU-60-24M-B-ST: Note, pre 1998 hoods are no longer available.

TSSU-72-30MB-ST-D2: Used standard after 11/20/05 production date although the 15 pan configuration is still an option. Check workorder to see if 15 pan configuration noted.

TSSU-60-12M-B: Note, pre 1998 hoods are no longer available.

TSSU-72-24M-B-ST: requires 2 per cabinet.

TSSU-72-12M-B: Note, pre 1998 hoods are no longer available.

TSSU-27-12MC-D-2: Note, pre 1998 hoods are no longer available.

TFP-32-12M-D2: N/A.

TFP-72-30M-D-6: N/A.

TFP-72-30M: N/A.

TFP-32-12M: N/A.