

Model-Specific Compatibility Notes [10/29/2014]:

TPP-93D-6: N/A

T-49F: N/A

TPP-93D-2: N/A

TWT-48: N/A

T-49: N/A

GEM-49: N/A

TUC-67D-4: N/A

T-49F-2-G-2: N/A

QA-60-24MB-L: N/A

TS-72FG: N/A

T-72-6: N/A

TS-49G-4: N/A

TSID-48-4: N/A

TC-72G: N/A

GDM-49DT: N/A

T-49FZ: N/A

GEM-69FC: If used on cooler built after 11/17/98 or serial number 1-2228669, will need 875570 bar to support the drain pan.

GDM-35: N/A

TUC-GAL-48-2: N/A

T-72G-6: N/A

TSSU-60-24M-DS: N/A

TSD-33: N/A

GDM-69: If used on cooler built after 11/17/98 or serial number 1-2228669, will need 875570 bar to

support the drain pan.

TSID-48-4-L: N/A

TUC-67D-2: N/A

TWT-67D-4: N/A

TS-72-6: N/A

TMC-49: N/A

TUC-27D-2: N/A

TMC-58-DS: N/A

GDM-69FC: If used on cooler built after 11/17/98 or serial number 1-2228669, will need 875570 bar to support the drain pan.

TC-72: N/A

TSID-72-2-L: N/A

TPP-93D-4: N/A

TWT-60D-4: N/A

GDM-41: N/A

TSSU-48-12: N/A

GDM-72: If used on cooler built after 11/17/98 or serial number 1-2228669, will need 875570 bar to support the drain pan.

GEM-49FC: N/A

GDM-60: N/A

TSSU-48-08: N/A

TUC-60G: N/A

T-72FG: N/A

T-72F: N/A

GDM-35RF: N/A

TSD-47G: N/A

TS-49-1-G-3: N/A

TSSU-48-8M: N/A

TSSU-72-30MB: N/A

TPP-60D-2: N/A

GEM-69: If used on cooler built after 11/17/98 or serial number 1-2228669, will need 875570 bar to support the drain pan.

TS-49G: N/A

T-35: N/A

TSSU-48-12M-B: N/A

TWT-72F: N/A

TS-35: N/A

TSSU-60-12: N/A

TSSU-60-16D-2: N/A

TSID-72-4: N/A

T-72FZ: N/A

GDM-47RL: N/A

TS-35F: N/A

TUC-48G: N/A

T-49FG: N/A

TPP-119: N/A

GEM-72: If used on cooler built after 11/17/98 or serial number 1-2228669, will need 875570 bar to support the drain pan.

T-49RL: N/A

TUC-44: N/A

TRCB-79: N/A

TWT-93D-6: N/A

TWT-44D-2: N/A

TS-49F-4: N/A

QA-72-30MB: N/A

T-35G: N/A

TRCB-50: N/A

TSSU-36-12M-B: N/A

TC-49: N/A

GEM-72FC: If used on cooler built after 11/17/98 or serial number 1-2228669, will need 875570 bar to support the drain pan.

T-49F-4: N/A

TSSU-27-08: N/A

TS-49-2-G-2: N/A

TSSU-60-10: N/A

GDM-45HL: N/A

TS-49F: N/A

TUC-60D-2: N/A

TUC-27FG: N/A

TSD-33G: N/A

TSSU-36-08: N/A

TSD-69: N/A

TSID-72-2: N/A

TS-49-4: N/A

TS-72: N/A

GDM-69RL: If used on cooler built after 11/17/98 or serial number 1-2228669, will need 875570 bar to support the drain pan.

TWT-27G: N/A

T-49G-RL: N/A

TS-72F: N/A

TSID-96-6: N/A

TSSU-27-12M: N/A

TS-35G: N/A

TUC-93D-6: N/A

TUC-36: N/A

TWT-48G: N/A

TRCB-79-86: N/A

TWT-27D-2: N/A

TSSU-60-24M-B: N/A

TSSU-60-24MB-DS: N/A

TMC-58: N/A

TSSU-48-12D-4: N/A

TUC-48F: N/A

TWT-36: N/A

TSSU-60-16: N/A

GDM-47: N/A

QA-48-18MB: N/A

T-49G-PT: N/A

TSSU-48-12M: N/A

TSSU-27-08F: N/A

TUC-27: N/A

TWT-27: N/A

T-72G: N/A

TSID-48-2: N/A

TS-72-3-G-3: N/A

TUC-72: N/A

TSSU-48-18M: N/A

TUC-36F: N/A

TSD-47: N/A

TWT-48D-4: N/A

GDM-33C: N/A

GDM-41C: N/A

TUC-27F-D-2: N/A

TWT-67D-2: N/A

GDM-47FC: N/A

GDM-37: N/A

TSID-48-2-L: N/A

TSSU-48-10: N/A

TUC-27G: N/A

TUC-48: N/A

TSD-69G: N/A

TUC-93: N/A

T-49G: N/A

TWT-27FG: N/A

TUC-60F: N/A

TSSU-48-15M-B: N/A

TWT-44: N/A

GDM-49RL: N/A

TUC-GAL-48: N/A

TC-49G: N/A

TUC-72F: N/A

TSID-96-3: N/A

TS-49FG: N/A

T-72F-6: N/A

TSSU-36-12M: N/A

TUC-GAL-48F: N/A

TWT-67: N/A

TUC-67: N/A

TSSU-72-30M: N/A

GDM-43F: N/A

TUC-60D-4: N/A

T-72: N/A

TUC-60: N/A

GDIM-49: N/A

TPP-44D-2: N/A

TWT-48F: N/A

T-49-2-G-2: N/A

TSSU-72-18D-2: N/A

TUC-27F: N/A

GDIM-72NT: N/A

TUC-60-32: N/A

TWT-60: N/A

TSSU-27-12M-C: N/A

TUC-48F-D: N/A

GDM-33: N/A

GDM-49: N/A

TSSU-60-16D-4: N/A

GEM-47FC: N/A

TUC-48D-4: N/A

TSSU-60-21M: N/A

GDM-72FC: If used on cooler built after 11/17/98 or serial number 1-2228669, will need 875570 bar to support the drain pan.

GDM-49W-RF: N/A

TUC-60-32D-2: N/A

TSSU-60-14: N/A

TS-49: N/A

TWT-60F: N/A

GDM-37HL: N/A

TSSU-72-30MB-DS: N/A

GEM-47: N/A

GDM-61: N/A

TPP-67D-4: N/A

GDM-49FC: N/A

TSSU-60-16-DS: N/A

TWT-60-32: N/A

GDM-69HL: N/A

GDIM-60: N/A

TSSU-48-18M-B: N/A

TWT-93: N/A

GDM-49RF: N/A

TS-72G-6: N/A

T-72-3-G-3: N/A

T-49DT: N/A

T-35F: N/A

TWT-72: N/A

T-35FZ: N/A

T-49G-4: N/A

TSSU-60-08: N/A

TWT-60G: N/A

TUC-44F: N/A

T-35FG: N/A

GDM-35F: N/A

TSID-72-4-L: N/A

TWT-36F: N/A

GDM-61FC: N/A

TSSU-60-24M: N/A

TWT-27F: N/A

TRCB-110: N/A

T-49-4: N/A

TPP-60: N/A

TSSU-27-08D-2: N/A

TPP-67: N/A

TPP-93: N/A

TSSU-72-18: N/A

TPP-67D-2: N/A

TPP-44: N/A

GDM-49F: N/A

GDM-72F: N/A

GDM-57: N/A

TSSU-48-15M: N/A

T-49PT: N/A

TS-72G: N/A

GDM-45: N/A

TWT-60-32D-2: N/A

TSSU-27-12M-B: N/A

TRCB-52: N/A

TPP-119D-8: N/A

TUC-67F: N/A

TUC-93F: N/A

TCGG-72: N/A

TSSU-72-10: N/A

TWT-93F: N/A

TUC-60-32F: N/A

TUC-48F-LP: N/A

TWT-67F: N/A

TWT-60-32F: N/A

TWT-27F-D2: N/A

TUC-48F-D-4: N/A

TWT-48F-D4: N/A

TUC-119: N/A

TWT-119: N/A

TSSU-72-30M-B-ST: N/A

TSSU-60-24M-B-ST: N/A

TWT-44F: N/A

TSSU-72-18-ST: N/A

TPP-119D-2: N/A

TPP-119D-4: N/A

TPP-119D-6: N/A

TUC-93D-4: N/A

TUC-119D-4: N/A

TUC-119D-6: N/A

TUC-119D-2: N/A

TUC-119D-8: N/A

TWT-119D-2: N/A

TWT-119D-4: N/A

TWT-119D-6: N/A

TWT-119D-8: N/A

TUC-44D-2: N/A

TUC-93D-2: N/A

TWT-93D-2: N/A

TWT-93D-4: N/A

TUC-48D-2: N/A

TWT-60D-2: N/A

TWT-48D-2: N/A

TSSU-60-16-DS-ST: N/A

TSSU-60-24M-B-DS-ST: N/A

TSSU-72-30M-B-DS-ST: N/A

TSSU-48-12D-2: N/A

TSID-72-3-L: N/A

TSID-72-6-L: N/A

GEM-61FC: N/A

TSID-72-3: N/A

TSID-72-6: N/A

TWT-67HD: N/A

TUC-44HD: N/A

TWT-44HD: N/A

TUC-44F-HD: N/A

TWT-44F-HD: N/A

TUC-67HD: N/A

TUC-67F-HD: N/A

TWT-67F-HD: N/A

TUC-93HD: N/A

TUC-93F-HD: N/A

TWT-93HD: N/A

TWT-93F-HD: N/A

TUC-60-32HD: N/A

TWT-60-32HD: N/A

TUC-60-32F-HD: N/A

TWT-60-32F-HD: N/A

TSSU-48-18MB-D4: N/A

TSSU-72-30MB-ST-D2: N/A

TSSU-60-16-ST: N/A

TSSU-72-18M-B: N/A

TSSU-72-16: N/A

TSSU-72-12: N/A

TSSU-72-08: N/A

TSSU-60-12M-B: N/A

TSSU-72-24M-B-ST: N/A

TRCB-52-60: N/A

GDM-49F FAMILY DOLLAR: N/A

GDM-72 FAMILY DOLLAR: If used on cooler built after 11/17/98 or serial number 1-2228669, will need 875570 bar to support the drain pan.

GDM-49 DOLLAR GENERAL: N/A

GDM-49F DOLLAR GENERAL: N/A

GEM-49 SUBWAY: N/A

TSSU-60-15M-B: N/A

TSSU-60-18M-B: N/A

TSSU-72-12M-B: N/A

TSSU-72-15M-B: N/A

GDM-72 DOLLAR GENERAL: If used on cooler built after 11/17/98 or serial number 1-2228669, will need 875570 bar to support the drain pan.

GDM-72F DOLLAR GENERAL: N/A

T-49-4PT: N/A

GDM-72F FAMILY DOLLAR: N/A

TSSU-27-12MC-D-2: N/A

TSSU-36-15MB: N/A

TSSU-72-12D-4: N/A

TSSU-72-18D-4: N/A

T-49MHC: N/A

TSSU-48-18MB-D2: N/A

TSSU-60-08D-2: N/A

TSSU-72-16-ST: N/A