

Model-Specific Compatibility Notes [04/28/15]

TPP-93D-6: Replaces the 958745 per PCN 7830. Replaces the 800303, 9531N376, 800313, 9531N335, 800397, 9531N393, 800337, 9531N374 ce; 800366 controls will require a relay.

TPP-93D-2: Replaces the 958745 per PCN 7830. Replaces the 800303, 9531N376, 800313, 9531N335, 800397, 9531N393, 800337, 9531N374 ce; 800366 controls will require a relay.

TWT-48: Per PCN 7830 replaces the 958745. Replaces the 800313, 9531N335, 800337, and 9531N374 controls. New control put into production 4/2002.

TUC-67D-4: Per PCN 7830 replaces the 958745. Replaces the 800313, 9531N335, 800337, and 9531N374 controls. New control put into production 4/2002.

TBB-3G: Per PCN 7830 replaces the 958745.

TUC-GAL-48-2: Per PCN 7830 replaces the 958745. Replaces the 800313, 9531N335, 800337, and 9531N374 controls. New control put into production 4/2002.

TSSU-60-24M-DS: Replaces 958745 per PCN 7830.

TBB-1: Per PCN 7830 replaces the 958745.

TUC-67D-2: Per PCN 7830 replaces the 958745. Replaces the 800313, 9531N335, 800337, and 9531N374 controls. New control put into production 4/2002.

TWT-67D-4: Per PCN 7830 replaces the 958745. Replaces the 800313, 9531N335, 800337, and 9531N374 controls. New control put into production 4/2002.

TMC-49: Replaces the 800313, 9531N335, 800337, and 9531N374 ce controls. New control put into production 4/2002.

TUC-27D-2: Replaces 958745 per PCN 7830 used before 11/2/14 per PCN 7881.

TPP-93D-4: Replaces the 958745 per PCN 7830. Replaces the 800303, 9531N376, 800313, 9531N335, 800397, 9531N393, 800337, 9531N374 ce; 800366 controls will require a relay.

TWT-60D-4: Per PCN 7830 replaces the 958745. Replaces the 800313, 9531N335, 800337, and 9531N374 controls. New control put into production 4/2002.

TSSU-48-12: Replaces 958745 per PCN 7830.

TSSU-48-08: Replaces 958745 per PCN 7830.

TUC-60G: Per PCN 7830 replaces the 958745. Replaces the 800313, 9531N335, 800337, and 9531N374 controls. New control put into production 4/2002.

TBB-3G-S: Per PCN 7830 replaces the 958745.

TDD-1-S: Per PCN 7830 replaces the 958745.

TSSU-48-8M: Replaces 958745 per PCN 7830.

TSSU-72-30MB: Replaces 958745 per PCN 7830 will use a relay.

TPP-60D-2: Replaces the 958745 per PCN 7830. Replaces the 800303, 9531N376, 800313, 9531N335, 800397, 9531N393, 800337, 9531N374 ce; 800366 controls.

TSSU-48-12M-B: Replaces 958745 per PCN 7830.

TSSU-60-12: Replaces 958745 per PCN 7830.

TSSU-60-16D-2: Replaces 958745 per PCN 7830.

TUC-48G: Per PCN 7830 replaces 7830. 115Vpacific production used before 2/2/05 or approximate serial no. 1-4057604. Building 9 used before 2/24/05 production date. Replaces the 800313, 9531N335, 800337, and 9531N374 controls. New control put into production 4/2002.

TUC-44: Per PCN 7830 replaces the 958745. 115Vonly used before 4/14/05 production date or approximate serial no. 1-4125084. All other voltates still used. Replaces the 800313)9531n335 & 800303)9531n374 & 800337)9531n374 controls. New control put into production 4/2002.

TWT-93D-6: Per PCN 7830 replaces the 958745. Replaces the 800313, 9531N335, 800337, and 9531N374 controls. New control put into production 4/2002.

TWT-44D-2: Per PCN 7830 replaces the 958745. Replaces the 800313, 9531N335, 800337, and 9531N374 controls. New control put into production 4/2002.

TSSU-27-08: Replaces 958745 per PCN 7830.

TSSU-60-10: Replaces 958745 per PCN 7830.

GDM-06: Per PCN 7830 replaces the 958745.

TUC-60D-2: Per PCN 7830 replaces the 958745. Replaces the 800313, 9531N335, 800337, and 9531N374 controls. New control put into production 4/2002.

TCM-78AC: Per PCN 7830 replaces the 958745.

GDM-05-S: Per PCN 7830 replaces the 958745.

TWT-27G: Per PCN 7830 replaces the 958745. Used before 11/2/14 per PCN 7881. Replaces the 800313, 9531N335, 800337, and 9531N374 controls. New control put into production 4/2002.

TSSU-27-12M: Replaces 958745 per PCN 7830.

TUC-93D-6: Per PCN 7830 replaces the 958745. Replaces the 800313, 9531N335, 800337, and 9531N374 controls. New control put into production 4/2002.

TUC-36: Used between 4/02 and 4/1/05 production date. Replaces the 9531n335 & 9531n374 controls.

TWT-48G: Per PCN 7830 replaces the 958745. Replaces the 800313, 9531N335, 800337, and 9531N374 controls. New control put into production 4/2002.

TWT-27D-2: Per PCN 7830 replaces the 958745. Used before 11/2/14 per PCN 7881. Replaces the 800313, 9531N335, 800337, and 9531N374 controls. New control put into production 4/2002.

TSSU-60-24M-B: Replaces 958745 per PCN 7830.

TSSU-60-24MB-DS: Replaces 958745 per PCN 7830.

TMC-58: 115V used between 4/2002 & ~5/10/2010 (PCN #4582) .

GDM-05PT-S: Per PCN 7830 replaces the 958745.

TSSU-48-12D-4: Replaces 958745 per PCN 7830.

TWT-36: Per PCN 7830 replaces the 958745. Replaces the 800313, 9531N335, 800337, and 9531N374 controls. New control put into production 4/2002.

TSSU-60-16: Replaces 958745 per PCN 7830.

TSSU-48-12M: Replaces 958745 per PCN 7830.

TUC-27: Replaces 958745 per PCN 7830 used before 11/2/14 per PCN 7881.

TWT-27: Per PCN 7830 replaces the 958745. Used before 11/2/14 per PCN 7881. Replaces the 800313, 9531N335, 800337, and 9531N374 controls. New control put into production 4/2002.

TUC-72: Per PCN 7830 replaces the 958745. Replaces the 800313, 9531N335, 800337, and 9531N374 controls. New control put into production 4/2002.

TSSU-48-18M: Replaces 958745 per PCN 7830.

TWT-48D-4: Per PCN 7830 replaces the 958745. Replaces the 800313, 9531N335, 800337, and 9531N374 controls. New control put into production 4/2002.

TWT-67D-2: Per PCN 7830 replaces the 958745. Replaces the 800313, 9531N335, 800337, and 9531N374 controls. New control put into production 4/2002.

TSSU-48-10: Replaces 958745 per PCN 7830.

TUC-27G: Replaces 958745 per PCN 7830 used before 11/2/14 per PCN 7881.

TUC-48: Per PCN 7830 replaces 7830. 115Vpacific production used before 2/2/05 or approximate serial no. 1-4057604. Building 9 used before 2/24/05 production date. Replaces the 800313, 9531N335, 800337, and 9531N374 controls. New control put into production 4/2002.

TUC-93: Per PCN 7830 replaces the 958745. will use a relay\nreplaces the 800313, 9531N335, 800337, and 9531N374 controls. New control put into production 4/2002.

TSSU-48-15M-B: Replaces 958745 per PCN 7830.

TWT-44: Per PCN 7830 replaces the 958745. Replaces the 800313, 9531N335, 800337, and 9531N374 controls. New control put into production 4/2002.

GDM-05PT: Per PCN 7830 replaces the 958745.

TUC-GAL-48: Per PCN 7830 replaces the 958745. Replaces the 800313, 9531N335, 800337, and 9531N374 controls. New control put into production 4/2002.

TWT-67: Per PCN 7830 replaces the 958745. Replaces the 800313, 9531N335, 800337, and 9531N374 controls. New control put into production 4/2002.

TUC-67: Per PCN 7830 replaces the 958745. Replaces the 800313, 9531N335, 800337, and 9531N374 controls. New control put into production 4/2002.

TSSU-72-30M: Replaces 958745 per PCN 7830 will use a relay.

TUC-60D-4: Per PCN 7830 replaces the 958745. Replaces the 800313, 9531N335, 800337, and 9531N374 controls. New control put into production 4/2002.

GDM-05: Per PCN 7830 replaces the 958745.

TUC-60: Per PCN 7830 replaces the 958745. Replaces the 800313, 9531N335, 800337, and 9531N374 controls. New control put into production 4/2002.

TPP-44D-2: Replaces the 958745 per PCN 7830. Replaces the 800303, 9531N376, 800313, 9531N335, 800397, 9531N393, 800337, 9531N374 ce; 800366 controls.

TSSU-72-18D-2: Replaces 958745 per PCN 7830 will use a relay.

TWT-60: Per PCN 7830 replaces the 958745. Replaces the 800313, 9531N335, 800337, and 9531N374 controls. New control put into production 4/2002.

TSSU-27-12M-C: Replaces 958745 per PCN 7830.

TBB-4G-S: Per PCN 7830 replaces the 958745.

TSSU-60-16D-4: Replaces 958745 per PCN 7830.

TUC-48D-4: Per PCN 7830 replaces 7830. 115Vpacific production used before 2/2/05 or approximate serial no. 1-4057604. Building 9 used before 2/24/05 production date. Replaces the 800313, 9531N335, 800337, and 9531N374 controls. New control put into production 4/2002.

TSSU-60-21M: Replaces 958745 per PCN 7830.

GEM-05: Per PCN 7830 replaces the 958745.

TSSU-60-14: Replaces 958745 per PCN 7830.

TSSU-72-30MB-DS: Replaces 958745 per PCN 7830 will use a relay.

TPP-67D-4: Replaces the 958745 per PCN 7830. Replaces the 800303, 9531N376, 800313, 9531N335, 800397, 9531N393, 800337, 9531N374 ce; 800366 controls.

TSSU-60-16-DS: Replaces 958745 per PCN 7830.

TWT-60-32: Per PCN 7830 replaces the 958745. Replaces the 800313, 9531N335, 800337, and 9531N374 controls. New control put into production 4/2002.

GDM-05RF: Per PCN 7830 replaces the 958745.

TSSU-48-18M-B: Replaces 958745 per PCN 7830.

TWT-93: Per PCN 7830 replaces the 958745. will use a relay\nreplaces the 800313, 9531N335, 800337, and 9531N374 controls. New control put into production 4/2002.

TBB-4G: Per PCN 7830 replaces the 958745.

TMC-34: Used before ~2/10/2010. Replaces the 800313, 9531N335, 800337, and 9531N374 ce controls. New control put into production 4/2002.

TWT-72: Per PCN 7830 replaces the 958745. Replaces the 800313, 9531N335, 800337, and 9531N374 controls. New control put into production 4/2002.

TSSU-60-08: Replaces 958745 per PCN 7830.

TWT-60G: Per PCN 7830 replaces the 958745. Replaces the 800313, 9531N335, 800337, and 9531N374 controls. New control put into production 4/2002.

TSSU-60-24M: Replaces 958745 per PCN 7830.

TRCB-110: N/A

TPP-60: Replaces the 958745 per PCN 7830. Replaces the 800303, 9531N376, 800313, 9531N335, 800397, 9531N393, 800337, 9531N374 ce; 800366 controls.

TSSU-27-08D-2: Replaces 958745 per PCN 7830.

TPP-67: Replaces the 958745 per PCN 7830. Replaces the 800303, 9531N376, 800313, 9531N335, 800397, 9531N393, 800337, 9531N374 ce; 800366 controls.

TPP-93: Replaces the 958745 per PCN 7830. Replaces the 800303, 9531N376, 800313, 9531N335, 800397, 9531N393, 800337, 9531N374 ce; 800366 controls will require a relay.

TSSU-72-18: Replaces 958745 per PCN 7830 will use a relay.

TPP-67D-2: Replaces the 958745 per PCN 7830. Replaces the 800303, 9531N376, 800313, 9531N335, 800397, 9531N393, 800337, 9531N374 ce; 800366 controls.

TPP-44: Replaces the 800313)9531n335 & 800303)9531n374 & 800337)9531n374 controls. New control put into production 4/2002.

TSSU-48-15M: Replaces 958745 per PCN 7830.

TDD-1: Per PCN 7830 replaces the 958745.

TWT-60-32D-2: Per PCN 7830 replaces the 958745. Replaces the 800313, 9531N335, 800337, and 9531N374 controls. New control put into production 4/2002.

TSSU-27-12M-B: Replaces 958745 per PCN 7830.

TBB-1-S: Per PCN 7830 replaces the 958745.

TSSU-27-08-LP: Replaces 958745 per PCN 7830.

TSSU-48-8-LP: Replaces 958745 per PCN 7830.

TSSU-48-10-LP: Replaces 958745 per PCN 7830.

TSSU-48-12-LP: Replaces 958745 per PCN 7830.

TSSU-60-08-LP: Replaces 958745 per PCN 7830.

TSSU-60-10-LP: Replaces 958745 per PCN 7830.

TSSU-60-12-LP: Replaces 958745 per PCN 7830.

TSSU-60-16-LP: Replaces 958745 per PCN 7830.

TSSU-60-16-DS-LP: Replaces 958745 per PCN 7830.

TSSU-27-08D-2-LP: Replaces 958745 per PCN 7830.

TSSU-48-12D-4-LP: Replaces 958745 per PCN 7830.

TSSU-60-16D-4-LP: Replaces 958745 per PCN 7830.

TSSU-27-12MB-LP: Replaces 958745 per PCN 7830.

TSSU-27-12MC-LP: Replaces 958745 per PCN 7830.

TSSU-48-12MB-LP: Replaces 958745 per PCN 7830.

TSSU-48-15MB-LP: Replaces 958745 per PCN 7830.

TSSU-48-18MB-LP: Replaces 958745 per PCN 7830.

TSSU-60-24MB-LP: Replaces 958745 per PCN 7830.

TSSU-60-24MB-DS-LP: Replaces 958745 per PCN 7830.

TUC-27-LP: Replaces 958745 per PCN 7830 used before 11/2/14 per PCN 7881.

TUC-36-LP: Used between 4/02 and 4/1/05 production date. Replaces the 9531N335 & 9531N374 controls.

TUC-48-LP: Per PCN 7830 replaces 7830. 115Vpacific production used before 2/2/05 or approximate serial no. 1-4057604. Building 9 used before 2/24/05 production date. Replaces the 800313, 9531N335, 800337, and 9531N374 controls. New control put into production 4/2002.

TUC-60-LP: Per PCN 7830 replaces the 958745. Replaces the 800313, 9531N335, 800337, and 9531N374 controls. New control put into production 4/2002.

TUC-27G-LP: Replaces 958745 per PCN 7830 used before 11/2/14 per PCN 7881.

TUC-48G-LP: Per PCN 7830 replaces 7830. 115Vpacific production used before 2/2/05 or approximate serial no. 1-4057604. Building 9 used before 2/24/05 production date. Replaces the 800313, 9531N335, 800337, and 9531N374 controls. New control put into production 4/2002.

TUC-60G-LP: Per PCN 7830 replaces the 958745. Replaces the 800313, 9531N335, 800337, and 9531N374 controls. New control put into production 4/2002.

TUC-27D-2-LP: Replaces 958745 per PCN 7830 used before 11/2/14 per PCN 7881.

TUC-48D-4-LP: Per PCN 7830 replaces 7830. 115Vpacific production used before 2/2/05 or approximate serial no. 1-4057604. Building 9 used before 2/24/05 production date. Replaces the 800313, 9531N335, 800337, and 9531N374 controls. New control put into production 4/2002.

TUC-60D-4-LP: Per PCN 7830 replaces the 958745. Replaces the 800313, 9531N335, 800337, and 9531N374 controls. New control put into production 4/2002.

TWT-27LP: Per PCN 7830 replaces the 958745. Used before 11/2/14 per PCN 7881. Replaces the 800313, 9531N335, 800337, and 9531N374 controls. New control put into production 4/2002.

TWT-48-LP: Per PCN 7830 replaces the 958745. Replaces the 800313, 9531N335, 800337, and 9531N374 controls. New control put into production 4/2002.

TWT-60LP: Per PCN 7830 replaces the 958745. Replaces the 800313, 9531N335, 800337, and 9531N374 controls. New control put into production 4/2002.

TWT-27D-2-LP: Per PCN 7830 replaces the 958745. Used before 11/2/14 per PCN 7881. Replaces the 800313, 9531N335, 800337, and 9531N374 controls. New control put into production 4/2002.

TWT-48D-4-LP: Per PCN 7830 replaces the 958745. Replaces the 800313, 9531N335, 800337, and 9531N374 controls. New control put into production 4/2002.

TWT-60D-4-LP: Per PCN 7830 replaces the 958745. Replaces the 800313, 9531N335, 800337, and 9531N374 controls. New control put into production 4/2002.

GDM-09PT: Per PCN 7830 replaces the 958745.

TDD-3G: Used before 8/29/03 and after 2/1/05 production date.

TSSU-72-10: Replaces 958745 per PCN 7830, will use a relay.

TBB-4G-PT: Per PCN 7830 replaces the 958745.

TSSU-72-30M-B-ST: Replaces 958745 per PCN 7830 will use a relay.

TSSU-60-24M-B-ST: Replaces 958745 per PCN 7830.

TDD-4G: Used after 2/1/05 production date.

TSSU-72-18-ST: Replaces 958745 per PCN 7830.

TUC-93D-4: Per PCN 7830 replaces the 958745. Replaces the 800313, 9531N335, 800337, and 9531N374 controls. New control put into production 4/2002.

TUC-44D-2: Per PCN 7830 replaces the 958745. 115V only used before 4/14/05 production date or approximate serial no. 1-4125084. All other voltages still used. Replaces the 800313)9531n335 & 800303)9531n374 & 800337)9531n374 controls. New control put into production 4/2002.

TUC-93D-2: Per PCN 7830 replaces the 958745. Replaces the 800313, 9531N335, 800337, and 9531N374 controls. New control put into production 4/2002.

TWT-93D-2: Per PCN 7830 replaces the 958745. Replaces the 800313, 9531N335, 800337, and 9531N374 controls. New control put into production 4/2002.

TWT-93D-4: Per PCN 7830 replaces the 958745. Replaces the 800313, 9531N335, 800337, and 9531N374 controls. New control put into production 4/2002.

TUC-48D-2: Per PCN 7830 replaces 7830. 115V pacific production used before 2/2/05 or approximate serial no. 1-4057604. Building 9 used before 2/24/05 production date. Replaces the 800313, 9531N335, 800337, and 9531N374 controls. New control put into production 4/2002.

TUC-48D-2-LP: Per PCN 7830 replaces 7830. 115V pacific production used before 2/2/05 or approximate serial no. 1-4057604. Building 9 used before 2/24/05 production date. Replaces the 800313, 9531N335, 800337, and 9531N374 controls. New control put into production 4/2002.

TWT-60D-2: Per PCN 7830 replaces the 958745. Replaces the 800313, 9531N335, 800337, and 9531N374 controls. New control put into production 4/2002.

TWT-60D-2-LP: Per PCN 7830 replaces the 958745. Replaces the 800313, 9531N335, 800337, and 9531N374 controls. New control put into production 4/2002.

TWT-48D-2: Per PCN 7830 replaces the 958745. Replaces the 800313, 9531N335, 800337, and 9531N374 controls. New control put into production 4/2002.

TUC-60D-2-LP: Per PCN 7830 replaces the 958745. Replaces the 800313, 9531N335, 800337, and 9531N374 controls. New control put into production 4/2002.

TSSU-60-16-DS-ST: Replaces 958745 per PCN 7830.

TSSU-60-24M-B-DS-ST: Replaces 958745 per PCN 7830.

TSSU-72-30M-B-DS-ST: Replaces 958745 per PCN 7830 will use a relay.

TSSU-48-12D-2: Replaces 958745 per PCN 7830.

TWT-67HD: Per PCN 7830 replaces the 958745. Replaces the 800313, 9531N335, 800337, and 9531N374 controls. New control put into production 4/2002.

TUC-44HD: Per PCN 7830 replaces the 958745. 115V only used before 4/14/05 production date or approximate serial no. 1-4125084. All other voltages still used. Replaces the 800313)9531n335 & 800303)9531n374 & 800337)9531n374 controls. New control put into production 4/2002.

TWT-44HD: Per PCN 7830 replaces the 958745. Replaces the 800313, 9531N335, 800337, and 9531N374 controls. New control put into production 4/2002.

TUC-67HD: Per PCN 7830 replaces the 958745. Replaces the 800313, 9531N335, 800337, and 9531N374 controls. New control put into production 4/2002.

TUC-93HD: Per PCN 7830 replaces the 958745. Replaces the 800313, 9531N335, 800337, and 9531N374 controls. New control put into production 4/2002.

TWT-93HD: Per PCN 7830 replaces the 958745. Replaces the 800313, 9531N335, 800337, and 9531N374 controls. New control put into production 4/2002.

TWT-60-32HD: Per PCN 7830 replaces the 958745. Replaces the 800313, 9531N335, 800337, and 9531N374 controls. New control put into production 4/2002.

TSSU-48-18MB-D4: Replaces 958745 per PCN 7830.

TSSU-72-30MB-ST-D2: Replaces 958745 per PCN 7830 will use a relay.

TSSU-60-16-ST: Replaces 958745 per PCN 7830.

TBB-GAL-3G: Per PCN 7830 replaces the 958745.

TSSU-72-18M-B: Replaces 958745 per PCN 7830 will use a relay.

TSSU-72-16: Replaces 958745 per PCN 7830, will use a relay.

TSSU-72-12: Replaces 958745 per PCN 7830, will use a relay.

TSSU-72-08: Replaces 958745 per PCN 7830, will use a relay.

TSSU-60-12M-B: Replaces 958745 per PCN 7830.

TSSU-72-24M-B-ST: Replaces 958745 per PCN 7830.

TRCB-96: N/A.

TSSU-60-15M-B: Replaces 958745 per PCN 7830.

TSSU-60-18M-B: Replaces 958745 per PCN 7830.

TSSU-72-12M-B: Replaces 958745 per PCN 7830, will use a relay.

TSSU-72-15M-B: Replaces 958745 per PCN 7830, will use a relay.

TCM-78AC-GF: Per PCN 7830 replaces the 958745.

TCM-78AC-GF-SD: Per PCN 7830 replaces the 958745.

TSSU-27-12MC-D-2: Replaces 958745 per PCN 7830.

TSSU-72-12D-4: Replaces 958745 per PCN 7830, will use a relay.

TSSU-72-18D-4: Replaces 958745 per PCN 7830 will use a relay.

TRCB-36: N/A.

TRCB-48: N/A.

TGW-3D-2: Replaces the 800393 per ft. 2152.

TGU-3D-2: Replaces the 800393 per ft. 2152.

TSSU-72-30M-B-D-2: Replaces 958745 per PCN 7830 will use a relay.

TSSU-48-18MB-D2: Replaces 958745 per PCN 7830.

TSSU-60-08D-2: Replaces 958745 per PCN 7830.

TSSU-72-40M-B-DS-ST: Replaces 958745 per PCN 7830 will use a relay.

TSSU-72-16-ST: Replaces 958745 per PCN 7830, will use a relay.

TUC-27-LP MCDSP1: Replaces 958745 per PCN 7830 used before 11/2/14 per PCN 7881.

TUC-27 MCDCF1: Replaces 958745 per PCN 7830 used before 11/2/14 per PCN 7881.