

991172 Compatibility Notes - 09/24/2015

Model	Notes
TWT-48	REPLACES THE 842050.
TBB-24-60G	REPLACES THE 842050.
TDD-3CT-S	REPLACES THE 842050.
TUC-67D-4	REPLACES THE 842050.
GDM-10PT	REPLACES THE 842050.
QA-60-24MB-L	REPLACES THE 842050.
TDD-2-S	REPLACES THE 842050.
TBB-3G	REPLACES THE 842050.
GDM-26W	REPLACES THE 842050.
TSID-48-4	REPLACES THE 842050.
GDM-49DT	REPLACES THE 842050.
TDD-4	REPLACES THE 842050.
TUC-GAL-48-2	REPLACES THE 842050.
GDM-23FC-RF	REPLACES THE 842050.
GDM-33SSL-54	REPLACES THE 842050.
TSSU-60-24M-DS	REPLACES THE 842050.
T-23-2	REPLACES THE 842050.
T-23-1-G-1	REPLACES THE 842050.
TSID-48-4-L	REPLACES THE 842050.
TUC-67D-2	REPLACES THE 842050.
TWT-67D-4	REPLACES THE 842050.
TMC-49	REPLACES THE 842050.
GDM-23RL	REPLACES THE 842050.
GDM-14SL	REPLACES THE 842050.
TR-31-2-G-2	REPLACES THE 842050.
TDD-2	REPLACES THE 842050.
TWT-60D-4	REPLACES THE 842050.
TSSU-48-12	REPLACES THE 842050.
GDM-35SL-60	REPLACES THE 842050.
GDM-26HL	REPLACES THE 842050.
GDM-41C-48	REPLACES THE 842050.
TSSU-48-08	REPLACES THE 842050.

TUC-60G	REPLACES THE 842050..
TBB-3G-S	REPLACES THE 842050.
TBB-24-48	REPLACES THE 842050.
GDM-41SL-54	REPLACES THE 842050.
TDD-4-S	REPLACES THE 842050.
GDM-19	REPLACES THE 842050.
TSSU-48-8M	REPLACES THE 842050.
GDM-26RF	REPLACES THE 842050.
TR-37RI	REPLACES THE 842050.
GDM-23	REPLACES THE 842050..
TPP-60D-2	REPLACES THE 842050.
GDM-29-SO	REPLACES THE 842050.
TBB-3-S	REPLACES THE 842050.
TR-31-2	REPLACES THE 842050.
TSSU-48-12M-B	REPLACES THE 842050.
TBB-24-GAL-48G-SD	REPLACES THE 842050.
TS-23-1-G-1	REPLACES THE 842050.
TSSU-60-12	REPLACES THE 842050.
TS-23G	REPLACES THE 842050.
TSSU-60-16D-2	REPLACES THE 842050.
TBB-24-72G	REPLACES THE 842050.
TBB-24-48G-SD	REPLACES THE 842050.
TUC-48G	REPLACES THE 842050.
TUC-44	REPLACES THE 842050.
TRCB-79	REPLACES THE 842050.
TWT-44D-2	REPLACES THE 842050.
GEM-19	REPLACES THE 842050.
GDIM-26NT	REPLACES THE 842050.
TDD-2CT-S	REPLACES THE 842050.
TM-25	REPLACES THE 842050.
GDM-23W	REPLACES THE 842050.
TRCB-50	REPLACES THE 842050.
GEM-23RF	REPLACES THE 842050.
TSSU-36-12M-B	REPLACES THE 842050.

GDM-10PT-LE	REPLACES THE 842050.
TDG-50-18	REPLACES THE 842050.
TS-23	REPLACES THE 842050.
TS-23G-RL	REPLACES THE 842050.
TBB-4	REPLACES THE 842050.
TSSU-60-10	REPLACES THE 842050.
TD-50-18	REPLACES THE 842050.
T-19G	REPLACES THE 842050.
TR-31	REPLACES THE 842050.
TDD-3	REPLACES THE 842050.
TUC-60D-2	REPLACES THE 842050..
TSSU-36-08	REPLACES THE 842050.
TCM-78AC	REPLACES THE 842050.
T-23G-2	REPLACES THE 842050.
TDG-65-24	REPLACES THE 842050.
T-49DT-G	REPLACES THE 842050.
TUC-36	REPLACES THE 842050.
TWT-48G	REPLACES THE 842050.
TRCB-79-86	REPLACES THE 842050.
TSSU-60-24M-B	REPLACES THE 842050.
TSSU-60-24MB-DS	REPLACES THE 842050.
TMC-58	REPLACES THE 842050.
TSSU-48-12D-4	REPLACES THE 842050.
TWT-36	REPLACES THE 842050.
TSSU-60-16	REPLACES THE 842050.
TBB-24-60	REPLACES THE 842050.
QA-48-18MB	REPLACES THE 842050.
TSSU-48-12M	REPLACES THE 842050.
TBB-24-72	REPLACES THE 842050.
TBB-24GAL-60	REPLACES THE 842050.
TS-19	REPLACES THE 842050.
TSID-48-2	REPLACES THE 842050.
TBB-24GAL-72	REPLACES THE 842050.
T-19	REPLACES THE 842050.

TSSU-48-18M	REPLACES THE 842050.
TBB-24GAL-48	REPLACES THE 842050.
TBB-2G	REPLACES THE 842050.
TWT-48D-4	REPLACES THE 842050.
GDM-33C	REPLACES THE 842050.
TWT-67D-2	REPLACES THE 842050.
GDM-23W-RF	REPLACES THE 842050.
TDD-3CT	REPLACES THE 842050.
TD-50-18-S	REPLACES THE 842050.
TR1R-1S	REPLACES THE 842050.
TSID-48-2-L	REPLACES THE 842050.
TBB-2-S	REPLACES THE 842050.
TSSU-48-10	REPLACES THE 842050.
TUC-48	REPLACES THE 842050.
GDM-23FC	REPLACES THE 842050.
T-23	REPLACES THE 842050.
TSSU-48-15M-B	REPLACES THE 842050.
TWT-44	REPLACES THE 842050.
TR1RRI89-1S	REPLACES THE 842050.
TUC-GAL-48	REPLACES THE 842050.
T-49DT-4	REPLACES THE 842050.
TR1RRI-1S	REPLACES THE 842050.
TBB-24GAL-48G	REPLACES THE 842050.
GDM-12PT	REPLACES THE 842050.
TSSU-36-12M	REPLACES THE 842050.
GDM-15	REPLACES THE 842050.
TWT-67	REPLACES THE 842050.
TS-49DT-G	REPLACES THE 842050.
TUC-67	REPLACES THE 842050.
TS-23-2	REPLACES THE 842050.
TUC-60D-4	REPLACES THE 842050..
TUC-60	REPLACES THE 842050.
GDM-26W-RF	REPLACES THE 842050.
TS-28-2-G-2PT	REPLACES THE 842050.

TPP-44D-2	REPLACES THE 842050.
TBB-4-S	REPLACES THE 842050.
TC-23G	REPLACES THE 842050.
TM-24	REPLACES THE 842050.
TUC-60-32	REPLACES THE 842050.
TWT-60	REPLACES THE 842050.
T-23G-RL	REPLACES THE 842050.
T-23G	REPLACES THE 842050.
TS-23G-2	REPLACES THE 842050.
GDM-35SL-RF	REPLACES THE 842050.
GDM-33SL-60	REPLACES THE 842050.
GDM-14RF	REPLACES THE 842050.
TBB-4G-S	REPLACES THE 842050.
TSSU-60-16D-4	REPLACES THE 842050.
TDD-4CT	REPLACES THE 842050.
TUC-48D-4	REPLACES THE 842050.
TSSU-60-21M	REPLACES THE 842050.
TR1R-2HS	REPLACES THE 842050.
TUC-60-32D-2	REPLACES THE 842050.
TSSU-60-14	REPLACES THE 842050.
TD-65-24-S	REPLACES THE 842050.
TBB-3	REPLACES THE 842050.
GDM-26	REPLACES THE 842050.
TD-65-24	REPLACES THE 842050.
GDM-23RF	REPLACES THE 842050.
TPP-67D-4	REPLACES THE 842050.
TBB-24-48G	REPLACES THE 842050.
TSSU-60-16-DS	REPLACES THE 842050.
TBB-2	REPLACES THE 842050.
GEM-23FC	REPLACES THE 842050.
TWT-60-32	REPLACES THE 842050.
TM-24-2	REPLACES THE 842050.
GEM-23	REPLACES THE 842050.
TSSU-48-18M-B	REPLACES THE 842050.

TBB-4G	REPLACES THE 842050.
TMC-34	REPLACES THE 842050.
TBB-2G-S	REPLACES THE 842050.
GDM-19FC	REPLACES THE 842050.
GDM-14	REPLACES THE 842050.
TDD-2CT	REPLACES THE 842050.
T-49DT	REPLACES THE 842050.
GDM-41SL-60	REPLACES THE 842050.
GDM-23HL	REPLACES THE 842050.
TSSU-60-08	REPLACES THE 842050.
TWT-60G	REPLACES THE 842050.
TSSU-60-24M	REPLACES THE 842050.
TC-23	REPLACES THE 842050.
GDIM-26	REPLACES THE 842050.
TPP-60	REPLACES THE 842050.
TR2DT-2S	REPLACES THE 842050 REFRIGERATOR SECTION.
TPP-67	REPLACES THE 842050.
TDD-3-S	REPLACES THE 842050.
TPP-67D-2	REPLACES THE 842050.
TPP-44	REPLACES THE 842050.
GEM-26	REPLACES THE 842050.
TSSU-48-15M	REPLACES THE 842050.
TR-56DT	REPLACES THE 842050.
TWT-60-32D-2	REPLACES THE 842050.
TDD-4CT-S	REPLACES THE 842050.
T-49DT-1-G-1	REPLACES THE 842050.
TBB-24GAL-60G	REPLACES THE 842050.
TBB-24GAL-60G-S	REPLACES THE 842050.
TS-28	REPLACES THE 842050.
TSSU-36-08-LP	REPLACES THE 842050.
TSSU-48-8-LP	REPLACES THE 842050.
TSSU-48-10-LP	REPLACES THE 842050.
TSSU-48-12-LP	REPLACES THE 842050.
TSSU-60-08-LP	REPLACES THE 842050.

TSSU-60-10-LP	REPLACES THE 842050.
TSSU-60-12-LP	REPLACES THE 842050.
TSSU-60-16-LP	REPLACES THE 842050.
TSSU-60-16-DS-LP	REPLACES THE 842050.
TSSU-48-12D-4-LP	REPLACES THE 842050.
TSSU-60-16D-4-LP	REPLACES THE 842050.
TSSU-36-12MB-LP	REPLACES THE 842050.
TSSU-48-12MB-LP	REPLACES THE 842050.
TSSU-48-15MB-LP	REPLACES THE 842050.
TSSU-48-18MB-LP	REPLACES THE 842050.
TSSU-60-24MB-LP	REPLACES THE 842050.
TSSU-60-24MB-DS-LP	REPLACES THE 842050.
TUC-36-LP	REPLACES THE 842050.
TUC-48-LP	REPLACES THE 842050.
TUC-60-LP	REPLACES THE 842050..
TUC-48G-LP	REPLACES THE 842050.
TUC-60G-LP	REPLACES THE 842050..
TUC-48D-4-LP	REPLACES THE 842050.
TUC-60D-4-LP	REPLACES THE 842050..
TWT-36LP	REPLACES THE 842050.
TWT-48-LP	REPLACES THE 842050.
TWT-60LP	REPLACES THE 842050.
TWT-48D-4-LP	REPLACES THE 842050.
TWT-60D-4-LP	REPLACES THE 842050.
TDB-24-48	REPLACES THE 842050.
TDD-3G	REPLACES THE 842050.
TA1R-1S	REPLACES THE 842050.
TA1R-2HS	REPLACES THE 842050.
TA1RRI-1S	REPLACES THE 842050.
TA1RRI89-1S	REPLACES THE 842050.
TA2DT-2S	REPLACES THE 842050.
TDB-24-48-1-G-1	REPLACES THE 842050.
TG1R-1S	REPLACES THE 842050.
TG1R-2HG	REPLACES THE 842050.

TG1RRI-1S	REPLACES THE 842050.
TG1RRI89-1S	REPLACES THE 842050.
TG2DT-2S	REPLACES THE 842050.
TDB-24-48G	REPLACES THE 842050.
TSSU-60-24M-B-ST	REPLACES THE 842050.
TDD-4G	REPLACES THE 842050 .
TUC-48D-2	REPLACES THE 842050.
TUC-48D-2-LP	REPLACES THE 842050.
TWT-60D-2	REPLACES THE 842050.
TWT-60D-2-LP	REPLACES THE 842050.
TWT-48D-2	REPLACES THE 842050.
TUC-60D-2-LP	REPLACES THE 842050..
TSSU-60-16-DS-ST	REPLACES THE 842050.
TSSU-60-24M-B-DS-ST	REPLACES THE 842050.
TSSU-48-12D-2	REPLACES THE 842050.
TM-24G	REPLACES THE 842050.
TR-31-1-G-1	REPLACES THE 842050.
TD-80-30	REPLACES THE 842050.
TWT-67HD	REPLACES THE 842050.
TUC-44HD	REPLACES THE 842050.
TWT-44HD	REPLACES THE 842050.
TUC-67HD	REPLACES THE 842050.
TUC-60-32HD	REPLACES THE 842050.
TWT-60-32HD	REPLACES THE 842050.
TSSU-48-18MB-D4	REPLACES THE 842050.
GDM-23-2	REPLACES THE 842050.
TR2DT-4HS	REPLACES THE 842050 REFRIGERATOR SECTION.
TSSU-60-16-ST	REPLACES THE 842050.
TBB-GAL-3G	REPLACES THE 842050.
TS-23PT	REPLACES THE 842050.
TG2DT-4HS	REPLACES THE 842050.
TBB-24-72-S	REPLACES THE 842050.
TSSU-60-12M-B	REPLACES THE 842050.
TDD-4CT-G	REPLACES THE 842050.

GEM-26 SUBWAY	REPLACES THE 842050.
TSSU-60-15M-B	REPLACES THE 842050.
TSSU-60-18M-B	REPLACES THE 842050.
TCM-78AC-GF	REPLACES THE 842050.
TA1R-1S STARBUCKS	REPLACES THE 842050.
GDM-33SSL-54	REPLACES THE 842050.
TCM-78AC-GF-SD	REPLACES THE 842050.
TDB-24-48-GAL-1-G-1	REPLACES THE 842050.
TSSU-36-15MB	REPLACES THE 842050.
TG1R-1S STARBUCKS	REPLACES THE 842050.
TBB-24GAL-72G	REPLACES THE 842050.
TR1RRI-1G	REPLACES THE 842050.
TA1RRI-1G	REPLACES THE 842050.
TG1RRI-1G	REPLACES THE 842050.
TBB-24-60G-SD	REPLACES THE 842050.
TBB-24GAL-72-S	REPLACES THE 842050.
TBB-24-48G-SD-S	REPLACES THE 842050.
TBB-24-60G-SD-S	REPLACES THE 842050.
TBB-24-72G-SD	REPLACES THE 842050.
GDM-19T	REPLACES THE 842050..
TBB-24-72G-SD-S	REPLACES THE 842050.
TA2DT-4HS	REPLACES THE 842050.
TBB-24-48-S	REPLACES THE 842050.
TBB-24-GAL-60G-SD	REPLACES THE 842050.
TBB-24-48G-S	REPLACES THE 842050.
TBB-24-60-S	REPLACES THE 842050.
TSSU-48-18MB-D2	REPLACES THE 842050.
TSSU-60-08D-2	REPLACES THE 842050.
STA1RRI-1S	REPLACES THE 842050.
STG1RRI-1S	REPLACES THE 842050.
STG2RRI-2S	REPLACES THE 842050.
STG2RRI89-2S	REPLACES THE 842050.
STR1RRI-1S	REPLACES THE 842050.
STR1RRI89-1S	REPLACES THE 842050.

TSSU-72-16-ST	REPLACES THE 842050.
---------------	----------------------