



EN  for making holes

1. Place the stencil for drilling holes over the location where you want the device to be mounted.
2. After ensuring the stencil is positioned correctly, including the direction you want the device to be facing, use a pencil to mark the outlines of the stencil onto the surface where you will mount the device.
3. Using a 12 mm drill bit, drill the holes for the mounting bolts. Then use the Jig Saw to cut out the area for everything else.