Use & Care Guide

INDUSTRIAL TABLES





ASSEMBLY/ARRIVAL

- It is the responsibility of the recipient to inspect the shipment for damage prior to signing the bill of lading. Damages must be reported to your authorized retailer within 5 days of receipt.
- 2. Inspect table top for damage before use.
- 3. Please refer to any safety labels on packaging or resources that come with table top.
- 4. Always follow cleaning and maintenance instructions.
- Assembly, if applicable, should be conducted by a qualified adult using the applicable instructions



STORAGE

1. After assembly, do not store upside down.



ONGOING MAINTENANCE

 Inspect all welds and fasteners on tables for damage before use. Ensure all legs are straight and touching the floor.

MONTHLY

 Tighten all bolts and screws, ensure structure is sound and there are no cracks/breaks in material. Do not overtighten – this may result in cracks in the material.





CLEANING INSTRUCTIONS

METAL PARTS

- Clean using a solution of mild soap or detergent with warm water. Recommended: Noble Lemon Lance (147LMNLANRQT).
- For dried-on dirt, clean with a soft brush and a mild cleaner. Recommended: Noble Spiffy Shine (999SPIFSHINE).
- Make sure metal is fully dry and clean before use to prevent rusting and other discoloration.
 As these may be the result of misuse, they may not be covered under warranty.

WOOD PARTS

- I. Do not use abrasive cleaners or products.
- Use a clean, soft cloth to dust furniture weekly.
 Dust in the direction of grain to prevent visible scratching.
- Clean with a mild soap and damp cloth and dry with a dry cloth. Recommended: Noble Sunbright (999SUNBRIGHT) and for deep cleaning, Noble LusterPlus (148LUSTER+).
- 4. If you are using a new soap or cleaner, test first on an area that may not be shown.
- Make sure wood is fully dry after cleaning and before use to prevent warping or damage to the finish. As these are the result of misuse, they may not be covered under warranty.



CAUTION

- . Always make sure table is stable and balanced.
- 2. Avoid scraping with sharp items/utensils.
- 3. Do not use if parts are broken or missing.