



Regency Cold Ceramic Cartridge Repair Kit for 600FW8 and 600PRW8 Series Faucets

#600CARTCOLD8



Technical Data

Cartridge Type	Ceramic
Features	NSF Listed NSF/ANSI 372 NSF/ANSI 61
Type	Cartridges Handle Components

Features

- Direct replacement for original part
- Contains cold side ceramic cartridge
- Blue "cold" index

Certifications



NSF/ANSI 61 & 372



CSA, US and Canada




NSF Listed

Notes & Details

This Regency cold ceramic faucet cartridge repair kit is a direct replacement for the one that came standard with select faucets. This kit contains a cold side ceramic cartridge.

This unit includes a ceramic cartridge, which provides a much lower fail rate than the compression cartridges widely used in the industry. In this design, 2 ceramic discs fit together to create a watertight seal when closed. This removes the need for a rubber seat washer, which is one of the most frequently replaced parts on a faucet.

 **WARNING:** This product can expose you to chemicals including lead, which are known to the State of California to cause cancer, birth defects, or other reproductive harm. For more information, go to www.p65warnings.ca.gov.