Date:



Project:

Regency Hot Ceramic Cartridge Repair Kit for 600FD4, 600FD8, 600FW4, and 600FW44GWH Series Faucets

Qty:

#600CARTHOT





Technical Data

Туре

Cartridge Type Ceramic Features

NSF Listed NSF/ANSI 372 NSF/ANSI 61

Cartridges Handle Components

Features

- Direct replacement for original part
- Contains hot side ceramic cartridge
- Red "hot" index •

Certifications



Notes & Details

This Regency hot ceramic faucet cartridge repair kit is a direct replacement for the one that came standard with select faucets. This kit contains a hot side ceramic cartridge.

This unit includes a ceramic cartridge, which provides a much lower fail rate than the compression cartridges widely used in the industry. In this design, 2 ceramic discs fit together to create a watertight seal when closed. This removes the need for a rubber seat washer, which is one of the most frequently replaced parts on a faucet.

WARNING: This product can expose you to chemicals including lead, which are known to the State of California to cause cancer, birth defects, or other reproductive harm. For more information, go to www.p65warnings.ca.gov.