



Regency Wall-Mounted Mop Sink Faucet with 6 1/2" Spout, 8" Centers, and Vacuum Breaker

#600FMS86



Technical Data

Spout Length	6 1/2 Inches
Faucet Height	14 1/2 Inches
Faucet Centers	8 Inches
Features	3/4" Garden Hose Thread NSF Certified Vacuum Breaker
Flow Rate	4 GPM
Handle Type	Lever
Material	Brass
Mounting Style	Wall Mounted

Features

- 6 1/2" spout
- 8" centers, 1/2" NPT inlets
- 3/4" garden hose outlet
- Wall-mounted base, attractive chrome-plated brass construction
- Lever handle design; includes vacuum breaker

Certifications



1/2" Water Connection




NSF Certified

Technical Data

Temperature Rating	140 Degrees F
Thread Type	NPT
Type	Faucets
Water Inlet Size	1/2 Inches

Plan View



Notes & Details

This convenient wall-mounted mop sink faucet features a 6 1/2" long heavy cast spout and lever handles, ideal for filling mop buckets for all of your janitorial tasks. As an added convenience, this mop sink faucet comes standard with a 3/4" garden hose thread and pail hook so you can extend the reach of your water supply and reduce strain on employees when filling up heavy pails. Plus, with the faucet's built-in vacuum breaker, your water supply will not be contaminated accidentally when you're mixing up chemicals.

The hot and cold lever-style handles are both labeled and color coded for easy identification, and a support rod attaches from the faucet to the wall mount in order to create a reliable hold. This faucet is intended for janitorial and dishwashing use only, making it great for schools, restaurants, grocery stores, and more. It requires 8" adjustable centers for installation. Check valves on the underside of each handle/stem make it easy to shut off water on one side of the faucet without having to shut off the whole water line leading to the faucet. This allows for quick and easy handle/stem replacement to get you back in service, sooner!

⚠️ WARNING: This product can expose you to chemicals including lead, which are known to the State of California to cause cancer and birth defects or other reproductive harm. For more information, go to www.p65warnings.ca.gov.