



Regency Wall Mount Faucet with 18" Double-Jointed Spout and 8" Centers

#600FW818DJ



Technical Data

Spout Length	18 Inches
Faucet Height	8 3/4 Inches
Cartridge Type	Stem
Faucet Centers	8 Inches
Features	California AB100 Compliant NSF/ANSI 372 NSF/ANSI 61
Finish	Chrome
Flow Rate	2 GPM
Handle Type	Lever

Features

- 18" double-jointed spout, 2 GPM aerator
- 8" centers, 1/2" NPT inlets
- Wall mounted base, attractive chrome-plated brass construction
- 140 degree maximum water temperature
- Lever handle design

Certifications



NSF/ANSI 61 & 372



CSA, US and Canada



NSF Listed




1/2" Water Connection

1/2"

Technical Data

Material	Brass
Mounting Style	Wall Mounted
Mounting Type	Adjustable
Spout Clearance	6 7/16 Inches
Spout Type	Double Jointed
Temperature Rating	140 Degrees Fahrenheit
Type	Faucets
Water Inlet Size	1/2 Inches

Plan View



Notes & Details

This Regency wall mount faucet with 18" double-jointed spout is an excellent choice when you need a reliable, affordable water fixture for your facility! Designed to be easy to install and easy to maintain, it's easy to see why Regency faucets are a great solution for any business. Thanks to an 18" double-jointed spout, this faucet delivers water exactly where you need it, and the hinged design gives maximum flexibility to fill multi-compartment sinks, while also letting you fold it out of the way when it's not being used. This is especially useful when you need to wash large and bulky cooking vessels.

Water exits the faucet through a 2 GPM aerator, which creates a soft flow pattern with minimal splashing. The faucet installs on your wall or sink backsplash on a pair of 8" centers and connects to the facility water lines with a set of 1/2" NPT inlets. The faucet body is made from chrome-plated brass that complements nearly any design aesthetic, and the water flow is controlled by a pair of simple lever handles. An installation kit is required for setup (sold separately).

⚠ WARNING: This product can expose you to chemicals including lead, which are known to the State of California to cause cancer, birth defects, or other reproductive harm. For more information, go to www.p65warnings.ca.gov.