



Regency Hot Ceramic Cartridge Repair Kit with Handle for 600FW8 and 600PRW8 Series Faucets

#600HHCRD8



Technical Data

Cartridge Type	Ceramic
Features	NSF Listed NSF/ANSI 372 NSF/ANSI 61
Type	Repair Kits

Features

- Direct replacement for original part
- Contains ceramic cartridge and faucet handle
- Hot handle index

Certifications



NSF/ANSI 61 & 372



CSA, US and Canada




NSF Listed

Notes & Details

This Regency hot ceramic faucet cartridge repair kit with handle is a direct replacement for the one that came standard with select faucets. This kit contains everything you need to quickly fix a hot-side handle in a convenient cartridge design that takes less time to replace than fixing individual components.

This unit includes a ceramic cartridge, which provides a much lower fail rate than the compression cartridges widely used in the industry. In this design, 2 ceramic discs fit together to create a watertight seal when closed. This removes the need for a rubber seat washer, which is one of the most frequently replaced parts on a faucet. It also includes a replacement handle with red hot index.

 **WARNING:** This product can expose you to chemicals including lead, which are known to the State of California to cause cancer, birth defects, or other reproductive harm. For more information, go to www.p65warnings.ca.gov.